Force HOBBS OCD (August 2007) MAY 11 2011

New Mexico Oil Conservation Division, District I

UNITED STATES

1625 N. French Drive

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

DEPARTMENT OF THE INTERIOR Hobbs, NM 88240 BUREAU OF LAND MANAGEMENT

5. Lease Serial No. NM0558287

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

Degraterse this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					,	
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well					•	
☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. Morgan A Federal #6	
2. Name of Operator Ridgeway Arizona Oil Corporation					9. API Well No. 30-041-10417	
3a. Address	3b. Phone No	. (include area co	ode)	10. Field and Pool or Exploratory Area		
200 N. Loraine, Suite 1440, Midland TX. 79701 432.6			.687.0303		Chaveroo-San Andres	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. Country or Parish, State	
I-27-07S-33E / 1980 FSL 660 FEL		Roosevelt Co. NN		Roosevelt Co. NM		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INI	ICATE NATUR	E OF NOTIC	E, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION			TY	PE OF ACT	ION	
Notice of Intent	Acidize	Deep	en	Produ	uction (Start/Resume)	Water Shut-Off
✓ Notice of Intent	Alter Casing	Frac	ture Treat	Recla	mation	✓ Well Integrity
Subsequent Report	Casing Repair	☐ New	Construction	Reco	mplete	Other
Subsequent Report	Change Plans	Plug	and Abandon	Temp	orarily Abandon	·
Final Abandonment Notice	Convert to Injection	Plug	Back	Wate	r Disposal	
MIRU PU/POOH w/down hole equip RIH w/bit/scraper to TD - check for f RIH w/RBP to 100 ft above top perf. If casing does not test - spot leak/per If casing tests - Remove RBP/RIH w Call BLM to witness MIT (8 5/8, 24# to 357' / 5 1/2, 14# to 44: ACCEPTED APPROVED FOR	ill - clean out as needed to test casing integrity of the common cernent squeeze/dr/tubing/packer - circulate 26 - perfs-4211-4287 - TE ONTH PERIOD	packer fluid	ond Run Ticl 0558287 Wa organ B Fed	s Due MA eral Ceas	oad Of Oil From Lo R 02 2011! Well N ed Production In I	lo. Paving
Quantities After NOV 2011 WILL Terminate If Production					on In Paving Quan	28/ Itities
		. Is No	ot Establishe	ed By MA	Y 27 2011!	
					-	· · · · · · · · · · · · · · · · · · ·
14. I hereby certify that the foregoing is tr	ue and correct. Name (Printe	d/Typed)				•
Andy Chalker			Title Operations Manager			
Signature Andy Chall			Date 04/08/20	011		
ACCEPTED FO	R RECHIS SPACE	FOR FEDE	RAL OR ST	ATE OFF	ICE USE	
Conditions of approval, if any, are attached that the applicant holds legal or equitable tientitle the applicant to conduct operations t	tle to those rights in the subject	not warrant or of the lease which we	ould Office			ate
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent Statements or representations.	SC Section 1212, make it a ENCINEER Sentations as to any matter with	crime for any p	erson knowingly a n.	nd willfully to	make to any department	or agency of the United States any false,

(Instructions on page 2)

SEE ATTACHED FOR CONDITIONS OF APPROVAL

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, call (575) 627-0205 or after office hours call (575) 420-2832.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)