Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <b>HOBBS</b> District II	<del></del>	30-025-10917
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	0 2011/220 South St. Francis Dr.	STATE FEE X
<u>District IV</u>	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	IVED	
SUNDRY NOTICES A (DO NOT USE THIS FORM FOR PROPOSALS T DIFFERENT RESERVOIR. USE "APPLICATION	AND REPORTS ON WELLS O DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name H LEONARD B
PROPOSALS.)  1. Type of Well: Oil Well Gas V	Vell X Other	8. Well Number 2
2. Name of Operator Chesapeake Operat		9. OGRID Number 147179
3. Address of Operator P.O. Box 18496		10. Pool name or Wildcat
Oklahoma City,	OK /3154	Jalmat; Tansill-Yates-Seven Rivers
4. Well Location		
Unit Letter D : 660'	feet from the North line and 60	
Section 32	Township 23 S Range 37 E Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Countylea
	13' GR	
12. Check Appro	priate Box to Indicate Nature of Notice	, Report or Other Data
TEMPORARILY ABANDON CHA	IG AND ABANDON ☐ REMEDIAL WO	RILLING OPNS. P AND A
OTHER:	☐ OTHER:	П
13. Describe proposed or completed of	perations. (Clearly state all pertinent details, an EE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
5/06/11: Move P&A unit from E W Wa 5/12/11: Spot equipment. RU P&A unit 2891'. 5/13/11: Circ hole w/plugging mud. PO unable to squeeze, pressure csng to 100 RIH to 1300'. Spot 30 sacks cmt. Displa 5/16/11: Tag TOC @ 902'. Perforate @ OK to spot cmt. POOH w/packer, RIH	llug & abandonment of this well from 5/06/11 the llden 6 to location. Dispatch anchor company to the location of the location	o test deadman anchors. h 2 3/8" tbg. Tag cmt on top of CIBP @  RIH w/packer to 930'. Load hole, set packer, (NMOCD), OK to spot cmt. POOH w/packer. and pressure to 700#. able to squeeze. Contact Mr. Mark Whitaker, wOC, Rig up WL. Tag TOC @ 240'. ge up WH. Squeeze cmt to surface. Turn well
Spud Date:	Rig Release Date: of C-10:	ed for plugging of well bore only. y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) hay be found at OCD Web Page under www.cmned.etate.mm.us/ved.
I hereby certify that the information above	is true and complete to the best of my knowled	ge and belief.
BA		
SIGNATURE My /Km	TITLE Sr. Regulatory Compl. Sp	DATE 05/18/2011
Type or print name Bryan Arrant For State Use Only	E-mail address: <u>bryan.arrant@c</u>	hk.com PHONE: (405)935-3782
- VI State OSC OHLY		
APPROVED BY:	TITLE STATE	VAR DATE 5-23-2011