

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

HOBBS OGD OIL CONSERVATION DIVISION

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240

1220 South St. Francis
Santa Fe, NM 87505

DISTRICT II
1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

MAY 24 2011

MAY 24 2011

RECEIVED

RECEIVED

WELL API NO. 30-025-37445
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Section 19
8. Well No. 733
9. OGRID No. 157984
10. Pool name or Wildcat Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	
4. Well Location Unit Letter <u>I</u> : <u>1690</u> Feet From The <u>South</u> <u>1080</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>18-S</u> Range <u>38E</u> NMPM Lea County	
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3655' GL	
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ Multiple Completion ☐ OTHER: _____ ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: Clean out/OAP/ acid treat ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- RUPU & RU.
- RU wireline & perforate tubing @4195'. RD wireline.
- ND wellhead/NU BOP.
- POOH and lay down ESP equipment.
- RIH with bit & drill collars. Tag @4500'. RU power swivel & stripper head. Drill cement & float collar from 4469-4500'(new TD). Circulate clean. RD power swivel & stripper head. POOH w/bit & drill collars.
- RU wireline & perforate hole @4435-4438', 4453-4484' @ 2 JSPF. RD wireline.
- RIH w/PPI packer. Acid treat well in 2 stages on new perms w/2000 gal of 15% NEFE acid.
- RU pump truck & pump 100 bbl fresh water w/60 gal of 6490 chemical. Flush w/100 bbl fresh water. RD pump truck.
- POOH w/PPI packer.

see attached sheet for additional data

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 05/18/2011
 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy.johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only

APPROVED BY [Signature] TITLE State Rep DATE 5-26-2011
 CONDITIONS OF APPROVAL IF ANY:

MAY 25 2011

NHU 19-733

10. RIH w/ESP equipment set on 130 jts of 2-7/8" tubing. Intake set @4558'.
11. ND BOP/NU wellhead.
12. RDPU & RU. Clean location and return well to production.

RUPU 04/21/2011

RDPU 04/29/2011

Wellbore Diagram : NHSAU 733-19

