	Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
~	District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised May 08, 2003 WELL API NO.	
	District II	OIL CONSERVATION DIVISION		30-025-36493	
	1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	· ·	STATE X FEE 6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM 87505			o. State Off & Gas Lease No.	
٠ſ	SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
	(DO NOT USE THIS FORM FOR PROPORTION OF PROP	SALS TO DRILL OR TO DEEPEN OR PL	JG BACK TO A		
	PROPOSALS.)	CATION FOR FERMIT (FORM C-101) FO	DK SUCH	AFT	
	1. Type of Well: Oil Well Gas Well	Other		8. Well Number #1 - Y	
ŀ	2. Name of Operator	-		9. OGRID Number	
	SOUTHWEST ROYALT	TIES, INC.		0 2 1 3 5 5	
	3. Address of Operator		10. Pool name or Wildcat		
ŀ	P.O. BOX 11390, 4. Well Location	MIDLAND, TEXAS	79702	CAPROCK, EAST DEVONIAN	
Unit Letter C: 760 feet from the NORTH line and 1935' feet from the WEST line					
	Section 2.6	Township 12-5 Ra	inge 32-E	NMPM LEA County	
	the state of the s	The second secon			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
				SEQUENT REPORT OF:	
	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		
	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL		
	PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB	ABANDONMENT	
	OTHER:		OTHER:	128	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dates of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RU BJ spot btm plug from 11,340' – 11,224' (146') w/30 sx class "H" cmt; tagged cmt, while good the completion of t				H" cmt; tagged cmt/(a)	
	11,203'; spot 2 nd plug from 10,125' – 10,025' – 10° w/25 sx class "H" cmt (verbal approval to				
	change procedures); spot 3rd plug from 7793' – 7693' – 100' w/25 sx class "H" cmt; spot 4th plug L vED				
	from 5681' – 5581' – 100' w/25 sx class "H" cmt; spot top plug from 3737' - 3617' – \\20' \text{w/35} \\\ sx class "C" cmt . Note: tagged @ 3707' (23' below 8-5/8" csg); re-spot top plug @ 36\\3' - \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				
	sx class "C cmt. Note: tagged @ 3707 (23" below 8-5/8" csg); re-spot top plug @ 36787 – 3553' (120') w/35 sx "C"; tag cmt @ 3604' – 80' above csg shoe @ 3604'. Completed $1\sqrt{28/04}$.				
	Released drilling rig. RIH w/tbg and cleaned out hole to 3631' (PBTD). RU WL and RIH				
	from 5681' – 5581' – 100' w/25 sx class "H" cmt; spot top plug from 3737' - 3617' – 120' w/35 Hobbs sx class "C" cmt. Note: tagged @ 3707' (23' below 8-5/8" csg); re-spot top plug @ 36/3' – 3553' (120') w/35 sx "C"; tag cmt @ 3604' – 80' above csg shoe @ 3604'. Completed 1/28/04. Released drilling rig. RIH w/tbg and cleaned out hole to 3631' (PBTD). RU WL and RIH w/GR/CCL and log well from 3544' – 2544'. Perforated 3140' – 3150'. Acidized w/250 gals 15% lead acid followed by 1000 gals mixed w/2 X 1.3 ball sealers per 100 gals. Swabbed no				
recovery; prepare to test upper Queen zone. WL set 8-5/8" CIBP @ 3110' and cap w/35' of class "C" cement. Perforated zone 3030' – 3069'. Pmpd 2000 gals 15% acid w/3 – 1.3 spec. grav. ball sealers; swb tested. Recovered load, no oil or gas shows. Prepare to P&A.					
				o P&A.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
5	SIGNATURE TITLE OPERATIONS ASSISTANT DATE 7/04				
		M. HOWARD dhowa	rd@swrinc	Telephone No. 432/686-9927	
(This space for State use)		·		
_	APPPROVED BY Land	U. Wink. TITLE		DATE	
C	APPPROVED BY				
	THE ITSTAFF MANAGER				