Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 October 13, 2009			
District to the	WELL API NO.	Jettober 13, 2009					
1625 N. French Dr., Hobbs, NM 88240 District II	RECEIVED	DIVICION	30-025-31566				
1301 W. Grand Ave., Artesia, NM 88210 Discrim III			 Indicate Type of Lease STATE				
1000 Rio Brazos Rd., Aztec, NM 87410	OBBSOC ^{Santa Fe, NM 87}	505	6. State Oil & Gas Lease No				
	JRR20Ch		o. State on & Gas Essay				
87505 SINDRY NOTIC	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agree	ement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Lovvington Paddock Unit				
PROPOSALS.) 1. Type of Well: Oil Well 🔯 C	8. Well Number 130						
2. Name of Operator	9. OGRID Number 241333						
Chevron Midcontinent, L. P. 3. Address of Operator			10. Pool name or Wildcat	/			
15 Smith Road Midland, TX 7970		Lovington Paddock					
4. Well Location							
Unit LetterJ:_				line			
Section 31	Township 16S	Range 37E		unty Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3820 GL							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF IN	TENTION TO: PLUG AND ABANDON □	SUB REMEDIAL WOR	SEQUENT REPORT O				
PERFORM REMEDIAL WORK	K ALTERING CASING ALLING OPNS. PAND A						
TEMPORARILY ABANDON DULL OR ALTER CASING	T JOB	. ப					
DOWNHOLE COMMINGLE	MULTIPLE COMPL	O' (O' (O' (O' (O' (O' (O' (O' (O' (O' (. 005	•			
		07.150.					
OTHER:	eted operations. (Clearly state all	OTHER:	d give pertinent dates, includin	g estimated date			
of starting any proposed wo	rk). SEE RULE 19.15.7.14 NMAG	C. For Multiple Co	mpletions: Attach wellbore dia	ngram of			
proposed completion or reco	impletion.		•				
Chevron respectfully requests approv	al to classify the subject well as te	mporarily abandone	ed. A five year TA status perio	d is requested.			
Proposed Procedure							
1. Pullout of hole with produc	tion equipment.						
2. Set CIBP @ 6080' and cap							
 Provide OCD 24 hours notice of the intent to perform MIT. Pressure test casing for 500 psi for 30 minutes. Record pressure test on paper chart. 							
4. Pressure test casing for 500 psi for 30 minutes. Record pressure test on paper chart.							
Rule 19.15.25.							
Set CIBP, RBP or Packer within 100 fe perfs. or open hole. Pressure test to 500		Condition	of Approval: Notify OCD H	lobbs			
a pressure drop of <u>not greater</u> than 10% over a Office 24 hours prior of running MIT Test & Chart							
30 minute period.							
Spud Date:	Rig Release D	ate:					
<u> </u>		<u> </u>					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE / Mald for							
Type or print name _Paul T. Brown E-mail address: paulbrown@chevron.com PHONE: 432-687-7351							
For State Use Only							
APPROVED BY Junah TITLE STANFINGE DATE 6-7-2011							
Conditions of Approval (if any):							
/ (

WELLBORE DIAGRAM LPU 130

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County: Status:	Lovingto 2300' FSI	By: PTB By: Paddock Unit n Paddock 1460' FEL St.: NM ducing Well	Well #: API Unit Ltr.: TSHP/Rng Pool Code Directions: Chevno:	OGRID:
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8 5/8" 24# 1325 500 yes surface 12-1/4"			KB: DF: GL: 3,820 Ini. Spud: 05/26/92 Ini. Comp.: 07/01/92
Production Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing 5 1/2" 15.5# 6530 1450 Yes Surface 7 7/8"			IBP @ 6080' capped w/ 50' erfs: 6130' - 6392'

PBTD - 6481'