

Submit 3 Copies to Appropriate District  
Office

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

1220 South St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

**OIL CONSERVATION DIVISION**  
1220 South St. Francis Drive  
Santa Fe, NM 87505

FORM C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-06743</b>
1. Type of Well: <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
2. Name of Operator <b>Apache Corporation</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>6120 S. Yale, Suite 1500 Tulsa, Oklahoma 74136-4224</b>		7. Lease Name or Unit Agreement Name <b>Northeast Drinkard Unit</b>
4. Well Location Unit Letter <b>F</b> : <b>1650</b> Feet From The <b>North</b> Line and <b>1650</b> Feet From The <b>West</b> Line Section <b>22</b> Township <b>21S</b> Range <b>37E</b> NMPM <b>Lea</b> County		8. Well No. <b>804</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3431' DF</b>		9. Pool name or Wildcat <b>Eunice Blinbry-Tubb-Drinkard-North</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b> <input type="checkbox"/> Perform Remedial Work <input type="checkbox"/> Plug and Abandon <input type="checkbox"/> Temporarily Abandon <input type="checkbox"/> Change Plans <input type="checkbox"/> Pull or Alter Casing <input type="checkbox"/> Other	<b>SUBSEQUENT REPORT OF:</b> <input type="checkbox"/> Remedial Work <input type="checkbox"/> Altering Casing <input type="checkbox"/> Commence Drilling Operations <input checked="" type="checkbox"/> Plug and Abandonment <input type="checkbox"/> Casing Test and Cement Job <input type="checkbox"/> Other

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/11/2004 Set cement retainer at 4462'. Pump 200 sx cement below retainer and leave 10 sx on top.  
Pull up to 4135' and pump 80 bbls plug mud.  
Spot cement plug from 2953' to 2685' with 45 sx. WOC and tagged @ 2685.

2/12/2004 Pump 145 bbls plug mud. Spot plug from 1200 - 1321' w/ 35 sx. WOC & tag.  
Spot plug from 285 - 148' w/ 35 sx. WOC & tagged @ 148'

2/16/2004 Spot surface plug w/ 10 sx. Installed P&A marker

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<u>Kara Coday</u>	TITLE	<u>Sr. Engineering Tech.</u>
DATE	<u>3/4/2004</u>	TELEPHONE NO.	<u>918-491-4957</u>
TYPE OR PRINT NAME <u>Kara Coday</u>			
(This space for State Use)			
APPROVED BY	<u>Lawrence Wink</u>	TITLE	<u>OC FIELD REPRESENTATIVE II/STAFF MANAGER</u>
DATE	<u>MAR 10 2004</u>		
CONDITIONS OF APPROVAL, IF ANY:			

MAR 10 2004