

Submit 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Avenue, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised March 25, 1999

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>WELL API NO.</b> 30-025-06042
<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>6. State Oil &amp; Gas Lease No.</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

**7. Lease Name or Unit Agreement Name:**  
  
L. Van Etten

**1. Type of Well:**  
 Oil Well  Gas Well  Other

**8. Well No.**  
2

**2. Name of Operator**  
Chevron USA Inc

**3. Address of Operator**  
15 Smith Rd, Midland, TX, 79705

**9. Pool name or Wildcat**  
Eumont, Yates, 7 Rvrs, Queen

**4. Well Location**  
 Unit Letter M : 660 feet from the South line and 660 feet from the West line  
 Section 9 Township 20-S Range 37-E NMPM Lea County

**10. Elevation (Show whether DR, RKB, RT, GR, etc.)**


**11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	Replug <input type="checkbox"/>

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 7" CIBP at 2400, spot 25sx, plug from 2400-2300 (Eumont, Yates, 7 Rvrs), Tag at 2273.
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL.
3. Spot 40sx, plug from 1230-1030 (9 5/8 Shoe, T-Salt), Tag at 1018.
4. Circ cmt from 250-Surf w/50sx (13" Shoe, Surf), Tag at Surf.
5. Install dry hole marker 2-26-04.

Approved as to plugging of the Well Bore.  
 Liability under bond is retained until  
 surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Manager/Sunset DATE 2/26/04

Type or print name Jimmy Bagley Telephone No. (432) 561-8600  
 (This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 23 2004  
 Conditions of approval, if any: