

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-26475
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Cambrian Management, LTD		6. State Oil & Gas Lease No. 33111
3. Address of Operator P.O. Box 272 Midland, TX 79702		7. Lease Name or Unit Agreement Name Lowe Land Company
4. Well Location Unit Letter <u>B</u> : <u>660</u> feet from the <u>north</u> line and <u>7980</u> feet from the <u>east</u> line Section <u>24</u> Township <u>13-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>		8. Well Number #1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3448.8 GR		9. OGRID Number 198688
		10. Pool name or Wildcat King, Wolfcamp

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

Approved as to plugging of the Well Bore.

Liability under bond is retained until ☐
surface restoration is completed.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-3-04 MIRU W/O rig and auxillary equipment

3-4-04 Spot 35 sx cmt 9760' - 9290'

3-5-04 RIH to 9760'. Spot 35 sx 9760 - 9290. WOC. Tag cement @ 9735'. Contact OCD to approve plug depth. Circ hole to surface w/ weighted fluid. Spot 25 sx 6110' - 5709'

3-6-04 Cut 4 1/2" csg @ 4950'. LD 16 jts

3-8-04 LD 93 jts 4 1/2" csg. Spot 50 sx 4995' - 4725'

3-9-04 Tag cmt @ 4739'. Spot 25 sx 2352' - 2252'. Spot 25 sx 480' - 380'. WOC. Respot 25 sx 480' - 380'.

3-10-04 Tag cmt @ 384'. Contact OCD to approve plug. Spot 10 sx 63' - surface. Cut off wellhead & deadman anchors. Weld on P & A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joe E. Crawford TITLE Operations Superintendent DATE 3/15/04

Type or print name Joe E. Crawford E-mail address: jcrawford@cambrianmgmt.com Telephone No. (432)-620-9181

(This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any: MAR 23 2004