

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-28506
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CONCHO RESOURCES INC.		6. State Oil & Gas Lease No.
3. Address of Operator 550 W. TEXAS, SUITE 1300 MIDLAND, TX 79701		7. Lease Name or Unit Agreement Name Mesa State
4. Well Location Unit Letter <u>J</u> : 1830 feet from the <u>South</u> line and 1980 feet from the <u>East</u> line Section <u>14</u> Township <u>16S</u> Range <u>35E</u> NMPM County <u>Lea</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3972.4		9. OGRID Number 193407
		10. Pool name or Wildcat North Shoebar-Wolfcamp

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☐ THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103

OTHER: TO BE APPROVED. ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Contact NMOCD 24 hrs. prior to commencement of abandonment.

1. MIRU. Unseat pump & POH LD rods & pump. NU 3M# manual dbl BOP. Release TAC & POH LD 346 jts 2 3/8" N80 EUE 8rd tbg & BHA.

2. RIH & set CiBP @ 10250'. Cap CIBP w/35' cmt.

3. PU w/s & RIH to 10200'. Circ & load hole w/9# mud. POH.

4. RU csg. jacks & free point 5 1/2" string. Make initial cut at 9000' & attempt to retrieve csg. If unable to pull from this point, obtain permission from NMOCD to attempt cut and pull at higher depth. POH & LD csg.

5. RIH w/w/s & spot 35 sx cmt plug f/8920' - 9050' (50' inside csg. stub). PU & WOC 2 hrs. RIH & tag.

6. PU & spot 35 sx cmt. plug f/6425'6525'.

7. PU & spot 45 sx cmt. plug f/4350'-4450'. PU & WOC 2 hrs. RIH & tag.

8. PU & spot 35 sx cmt. plug f/2000 - 2100'.

9. PU & spot 35 sx cmt. plug f/457'-557'. PU & WOC 2 hrs. RIH & tag.

10. PU to 30' & spot 10 sx surface plug. POH.

11. Cut off wellhead. Weld on plate & DH marker. Back fill cellar.

12. RDMO Csg. Pullers

13. MO all equipment and clean location and set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda Coffman TITLE REGULATORY ANALYST DATE 03/19/2004

Type or print name BRENDA COFFMAN

E-mail address:

BCOFFMAN@CONCHORESOURCES.COM

Telephone No. (432)685-4373

(This space for State use)

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY May W. Wink TITLE

DATE

Conditions of approval, if any:

MAR 23 2004