

C.L. CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Pennzoil Company	8. Farm or Lease Name Stanfield
3. Address of Operator P.O. Drawer 1828 - Midland, Texas 79702-1828	9. Well No. 1
4. Location of Well UNIT LETTER K, 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 7-N RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Wildcat
11. Elevation (Show whether DF, RT, GR, etc.) 4599.6 Ground	12. County Curry

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPMS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-22-84 Prep to P&A
3-28-84 M.I. Caffey Plugging Unit
3-29-84 Cut 9 5/8" csg @ 2000'. Worked & pulled.
3-30-84 POOH w/ 9 5/8" csg & L.D. total of 47 jts 9 5/8" 36#/ft K-55 csg. Circ'd hole w/ 10 ppg salt mud. Mixed & pmp'd 100 sx Class "C" cmt. Set plug from 2047' to 1903'. POOH w/ tbg. WOC.
3-31-84 WIH w/ 2 3/8" work string OE. Tag'd plug @ 1918'. POOH w/ tbg to 834'. Loaded hole w/ 10 ppg mud. Mixed & pmp'd 100 sx C1 "C" cmt. Plug set @ 834' to 700'. POOH w/ 2 3/8" tbg.
4-2-84 WIH w/ 2 3/8" tbg. Tag'd plug @ 726'. POOH & L.D. tbg. Set 10 sx plug in 13 3/8" csg at surface. Welded steel plate on 13 3/8" & installed dry hole marker. R.D. Well P&A. Final Report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ernest Phadry TITLE Engineering Assistant DATE 4-17-84

APPROVED BY Ronald M. Coulter TITLE OIL & GAS INSPECTOR DATE AUG 28 1986

CONDITIONS OF APPROVAL, IF ANY:

APR 19 1984
O.C.D.
HOEBS OFFICE