

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator LARIO OIL & GAS CO.		8. Farm or Lease Name State "B"
3. Address of Operator P.O. Box 155, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER P , 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 1 TOWNSHIP 9-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat Flying M - San Andrew
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-21-74 Move in and rig up

2-25-74 Run and set a C.I.B.P. @4335' Dump 35 sacks of cement on C.I.B.P. with a dump bailer from 4335'-4300'

2-26-74 Circulate hole with mud laden fluid, Shot 4 1/2 casing @3597' Pull and lay down casing.

2-27-74 Run tubing to 3597' and pump a 35 sack plug. Pull tubing to 3715 35 sack plug across 8-5/8 casing shoe.

2-28-74 Shot 8-5/8 casing @397'. Pump a 75 sack plug, Pull tubing and pump a 10 sack top plug

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Richard D. Carr

TITLE P & A MANAGER

DATE March 8, 1974

APPROVED BY A. H. Statton

TITLE OIL & GAS INSPECTOR

DATE JUL 24 1974

CONDITIONS OF APPROVAL, IF ANY: