

LEA FISHING TOOLS, INC.

BOX ~~XXX~~ 1526

PHONE EX 3-2415

HOBBS, NEW MEXICO

10-7-73

RIG UP PULLING UNIT RUN 5 3/4" O.D. BOWEN OVERSHOT WITH KUTRITE FLUTED MILL GUIDE WITH BOWEN OIL JARS & BUMPER SUB & 4 - 3 1/2" DRILL BOLLARS. UNABLE TO CATCH FISH. PULL OUT OF HOLE. RUN 6" KUTRITE ROTARY SHOE 10' OF 5 1/2" WASHPIPE. RUN INTO HOLE AND USING TONGS & BAKER TUBING SWIVEL WASH OVER FROM 1421' TO 1431'. SHUT WELL IN FOR NIGHT.

10-8-73

CONTINUE MILLING WITH SHOE TO 1436'. PULL OUT OF HOLE RUN 5 3/4" BOWEN OVERSHOT WITH OVERSHOT EXTENTION & KUTRITE MILL GUIDE. MILL OVER FISH & JAR 3 JOINTS OUT. PULL OUT, OF HOLE SHUT WELL IN FOR NIGHT.

10-9-73

RUN 6 1/2" LEAD BLOCK. GET IMPRESSION OF SUB ABOVE SWAGE. RUN JARS BUMPER SUB & 5 3/4" BOWEN OVERSHOT. LATCH ONTO JAR OUT SWAGE. RERUN 5 3/4" O.D. OVERSHOT WITH EXTENTION WITH 2 3/8" GRAPPLE. SHUT WELL IN FOR NIGHT.

10-10-73

PULL OUT OF HOLE WITH OVERSHOT. NO FISH. RUN 5 3/4" O.D. KUTRITE ROTARY SHOE. GO DOWN BESIDE FISH. RUN 5 3/4" O.D. KELO SOCKET. GO DOWN BESIDE FISH. SHUT WELL IN FOR NIGHT.