

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1106

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State SR "B"
3. Address of Operator Drawer "D", Monument, New Mexico 88265	9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 9-S RANGE 32-E NMPM.	10. Field and Pool, or Wildcat SRR Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 4344' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted 30 sx. cement plug from 10,965' to 11,085'. Cut off 5-1/2" casing at 6600'. Spotted 25 sx. cement plug from 6542' to 6600', 25 sx. cement plug from 4802' to 4860'. Spotted 30 sx. cement plug in 8-5/8" casing and 7-7/8" hole from 3505' to 3595'. Cut off 8-5/8" casing at 600'. Spotted 40 sx. cement plug from 525' to 625', 40 sx. cement plug from 313' to 363' and 10 sx. cement plug from 0' to 11'. Installed dry hole marker and cleaned location. Well P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>Supver., Admin. Services</u>	DATE <u>10-24-73</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>DEC 1973</u>
CONDITIONS OF APPROVAL, IF ANY: <u></u>		