

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <i>Chase</i> Chase Petroleum Corp. 3. Address of Operator P. O. Drawer 2358, Midland, Texas 79701 4. Location of Well UNIT LETTER <u>A</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>10 S</u> RANGE <u>32 E</u> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name Zapata State 9. Well No. 1 10. Field and Pool, or Wildcat N. Mescalero Cisco
15. Elevation (Show whether DF, RT, GR, etc.) 4333 Gr.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run CIBP at 8758 and capped it with 35' of cement.
2. RIH with tbq. and circ. with mud laden fluid.
3. Cut 5½ csg. at 5250 POH. Tagged plug at 4880.
4. Spotted 55 sax plug at 3524. Tagged at 3418.
5. Spotted a 40 sax plug at 413 to 313.
6. POH Cut off well head and spot surf. plug. Installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>[Signature]</i>	TITLE <u>Agent</u>	DATE <u>12-13-78</u>
APPROVED BY <i>[Signature]</i>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JUN 26 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		