

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
E 9713

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Disposal Well	7. Unit Agreement Name
2. Name of Operator Sage Energy Company	8. Farm or Lease Name No Pit Pete SWD
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>510</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) NA	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Attempt to clean well up (fish) to at least T/Glorieta (5000'±) If well will take fluid a retainer will be set as deep as possible with minimum depth at 4200'.

- Plug No. 1 200 sxs plug will be displaced to perms from this pt. Cut 5½" at 4000±.
- Plug No. 2 100' plug in 5½" stub (1/2 in and 1/2 out) at 4000'±.
- Plug No. 3 100' plug at 9 5/8" shoe - 3476'.
- Plug No. 4 - 100' plug B/salt - 2100' in 9 5/8"
- Plug No. 5 - 100' plug T/salt - 1650' in 9 5/8"
- Plug No. 6 - 100' plug at 13 3/8" shoe 471'
- Plug No. 7 - 10 sxs surface plug.
P&A Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Clerk DATE April 18, 1985

ORIGINAL SIGNED BY RESBY SEXTON
DISTRICT 1 SUPERVISOR

APR 23 1985

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 22 1985

O.C.D.
HOBBS OFFICE