DISTRIBUTION			 1
SANTA FE			 Ì
FILE			NE
U.S.G.S.			
LAND OFFICE			 J
TRANSPORTER	OIL		
	GAS		
PRORATION OFFIC	E]
OPERATOR		3	

. 🔽

EW MEXICO OIL CONSERVATION COMMISSION

(Form C-102) (Revised 7/1/52)

Radi

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	·
NOTICE OF INTENTION TO PLUG WELL		Notice of Intention to Plug Back	x	Notice of Intention to Set Liner	
Notice of Intention to Squeeze	X	Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	x	Notice of Intention (Other)		Notice of Intention (Other)	

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

County

Hobbs, N. M. (Place) June 7, 1963

(Date)

Gentlemen:

Sumray DX 011 Company N. N. State "K" 1 (Company or Operator) in SW 1/4 SE 1/4 Of Sec. 1 T 108 R 108 NMPM. North Mescalero	Following is a Notice of Intention to do certain work as described below at the					
	Sunray DX 011 C	ompany N. M.	State "K"			0
(40-acre Subdivision)	SW 1/4 SE	14 of Sec. 11	, <mark>T. 108</mark>	, R,NMPM.,	North Mescalero	(Unit) Pool

Recomplete from Atoka to Wige FULL DETAILS OF PROPOSED PLAN OF WORK

- 1. MI derrick unit. Kill W/Wir. Install BG. Full tog. Drop trip bob on Hod D. Spot 2 ax cat on top trip bob w/WL dump bailer. Run LW GR-N log 8900' - 8200' and 4500' - 3900', regular and detail scales.
- 2. Perf 4 holes @ 8848 (Schl GR meas.) Run the w/FB and test cant plug on Mod D to 2000#. Pall back FB and sq cant w/50 ax Incor Pos batches as req (Howso). Run the gun and perf 4 holes @ 8696 and sq cant as before. Ditto squeese on 4 holes @ 8300. Drill out squeese plugs and test to 2000#. Perf 2' sections, 2 holes/ft in interval 8700-8840' as selected from GR-H log. Keep number of sections perf'd to a minimum and sections as far spart as practical to allow individual testing/plugging if needed. Run the w/FB and acidime w/1000 gal Dowell BDA. Drop balls (equal in No. as perfs) continuously thru treatment. Such and test as necessary for evaluation of interval. May need to run retrievable BP and/or do additional treating. For additional treating, anticipate XM38 and then acid petrofrac w/volumes dependent on previous vels and feet perf'd. If interval proves non-commercial, sq cant w/100 ax batches Incor Pos as required.
- 3. If previous completion interval is capable of strong flow at top allowable (108 HOPD w/36 unit

COR	tinued on reverse sloe
Approved, 19.	Company op Operator
Except as follows:	By K Mayabb V.R.Kayabb
	District Angineer Position
Approved	Send Communications regarding well to:
OIL CONSERVATION COMMISSION	
By	Name
Tiple	Address SIX P. O. Box 128, Hobbs, N. N.
1 159	

continued from reverse side ...

pull test packer and run back w/Baker Mod R and set approx 50' above top perf. If previous completion interval has recoverable cil but does not appear to be long life top allowable, set retr HP above top perf and cap w/20' sand. Ferf two-foot sections in interval 8300-8700 w/selection, number, and spacing similar to Step Ho. 2. Treatment and evaluation of sections will also be similar to Step Ho. 2. If ame interval will flow and other won't, may separate flowing interval and produce separate until more equal to other interval.

4. Final completion equipment will depend on fluids obtained. If pumping required, run 2-3/8" tbg, 7/8 and 3/4 rods, and 14" pump for volumes of less than about 200 BPD.