NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C. C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		da. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		9943
(DO NOT USE THIS FORM FO USE "APPI	NDRY NOTICES AND REPORTS ON WELLS IN PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. LICATION FOR PERMIT	
1. OIL GAS WELL WELL	UTHER-	7. Unit Agreement Name
2. Name of Operator		8, Farm or Lease Name
Cities Servic	State AD	
3. Address of Operator		9. Well o. <b>#1</b>
P. O. Box 69	- Hobbs, New Mexico 88240	₩ <b>₩</b>
4. Location of Well		10, Field and Pool, or Wildcat
UNIT LETTER	660FEET FROM THELINE AND 1980FEET FROM	Mescalero Permo Penn
UNIT LETTER		
tue East Line s	SECTION 22 TOWNSHIP 105 RANGE 32E NMPM	
175 UNE, 3		×/////////////////////////////////////
TTTTTTTTTTTTTTTTTTTTTTT		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4345	12. County
	4345	Lea
	4345 eck Appropriate Box To Indicate Nature of Notice, Report or Ot	Lea Allili
	4345 eck Appropriate Box To Indicate Nature of Notice, Report or Ot	Lea
	4345 eck Appropriate Box To Indicate Nature of Notice, Report or Ot	Lea Allili
	4345 eck Appropriate Box To Indicate Nature of Notice, Report or Ot SUBSEQUEN	Lea her Data T REPORT OF:
PERFORM REMEDIAL WORK	4345 eck Appropriate Box To Indicate Nature of Notice, Report or Ot of INTENTION TO: Plug and abandon Remedial Work	Lea her Data T REPORT OF:
PERFORM REMEDIAL WORK	4345 eck Appropriate Box To Indicate Nature of Notice, Report or Ot of INTENTION TO: Plug and abandon Remedial work commence drilling opns.	Let her Data T REPORT OF: A_TERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	4345 ECK Appropriate Box To Indicate Nature of Notice, Report or Ot SUBSEQUEN PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	Les her Data T REPORT OF: Autering casing plug and abandonment

This well was originally completed as Devonian producer through perforations 9795-9820. Well went to 100% water and was recompleted as a Penn producer. The Devonian was plugged off with a cast iron bridge plug at 9506 with one sack cement dumped on top from 9506 to 9498. The Penn formation was completed with one hole at each of the following depth; 9298, 9307, 9313, 9321, 9346, 9353, 9360, and 9326. Subsequently the casing collapsed @ 7407. We proposed to plug well in the following manner:

- Set cast iron coment retainer at 7290. Displace 90 sacks coment below retainer. Seat sealing bar in retainer, and displace 10 sacks on top of retainer from 7390 to 7310.
- 2. Cut off and recover  $5\frac{1}{2}$  casing. Estimated recovery 5000'.
- 3. Displace 50 sack cement plug at  $5\frac{1}{2}$ " casing stub (one sack of cement fills up 3.25" in 7 7/8" hole. Plug will be 160" long)
- 4. Displace 50 sack cement plug across lowest producing zone in San Andres from 4263 to 4100.
- 5. Displace 50 sack plug  $\frac{1}{2}$  in and  $\frac{1}{2}$  out of 8 5/8" intermediate casing from 3545 to 3395.
- 6. Put 10 sack plug in top of 8 5/8" intermediate casing from bottom of cellar to 30", and install 4" pipe marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE	District Clerk	DATE January 11, 1967

DATE

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY