

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-00042

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
40A LH 2022; 280 ac V-3833

7. Lease Name or Unit Agreement Name

State Com Unit No. ~~1~~

8. Well No.
1

9. Pool name or Wildcat
East Caprock Mississippian Gas P.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

W.O.G., Inc.

3. Address of Operator

P. O. Box 1813, Midland, TX 79702

4. Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 11

Township 11S

Range 32E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4343' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig-up
2. Pull 2 7/8' Tubing
3. Free point and cut 5 1/2" casing at approximately 6000' to 7000'. POH with casing
4. Spot 100' Class H cement plug at casing stub. Half in casing and half out
5. Spot 100' Class H cement plug at base of 9 5/8" casing (3515') 3565'-3465' tag & plug
6. Spot 100' Class H cement plug inside 9 5/8' casing from 435--335'.
7. Spot 10 sx Class H cement surface plug and weld capon.
8. Install P&A marker, cut off anchors and clean up location. Will advise when ready for final inspection.

CIBP w/ 35 ft cement above CIBP or
100 ft cement plug (w/ 25 sx minimum) within 100' of
perform MUST TAG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Linda Johnston

TITLE

Agent

DATE 12/22/93

TYPE OR PRINT NAME

Linda Johnston

TELEPHONE NO. (915) 685-07

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

DATE DEC 29 1993