was perforated from 10,030' to 10,120' with & shots per foot. Treated formation through perforations from 10,080' to 10, 120' with 500 gale. of mud acid. Subbed load oil and small amount of gas in 12 hours. Formation was then hydrafraced through performations from 10,030' to 10,120' with 1500 gallons. Swabbed hydrafrac and 40 obls. of load oil in 20 hours.

A bridging plug was then set at 10,069' with 1 sack of calseal on top of plug. Casing was perforated from 9,980' to 10,064' with 5 shots per foot. After washing perforations with 500 gellons of sud asid, formation was treated through perforations with 2,250 gallons of Stratafrae, Swabbed 29 bols, of load oil in 5 bours.

a bridging wing was then set at 9,890 with six socks of calceal on top of plug. Casing was perforsted from 9,730' to 9,640 with 4 shots per foot. After weshing perforstions with 500 gallons of mud acid well biebed off and flowed gas, on test well flowed 50 b 1s. of oil in 8 hours through a 24/64" choke.