

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 6126	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- P&A - Re-Entry		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Yates Petroleum Corporation		Winter Queen State Unit
3. Address of Operator		9. Well No.
105 South 4th St., Artesia, NM 88210		
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER 0 660 FEET FROM THE South LINE AND 1933 FEET FROM		Caprock Queen
THE East LINE, SECTION 3 TOWNSHIP 12S RANGE 32E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4405.8' GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-20-88. Plugged well as follows:

WIH with tubing to 3100'. Spot 50 sack cement plug. Waited 2 hrs and tagged plug 2150'. Witnessed by Ray Smith, NMOC, Hobbs, NM. Laid down tubing to 388'. Spot 35 sack cement plug. Laid down tubing. Spot 15 sacks surface plug. Installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jack Griffin</u>	TITLE <u>Production Supervisor</u>	DATE <u>12-27-88</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>OCT 2 1989</u>
CONDITIONS OF APPROVAL, IF ANY:		