

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- S.W.D.	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator Drawer D, Monument, New Mexico 88265	
4. Location of Well UNIT LETTER I 660 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 11 TOWNSHIP 12S RANGE 32E NMPM.	

7. Unit Agreement Name
8. Farm or Lease Name East Caprock S.W.D.
9. Well No. 1
10. Field and Pool, or Wildcat East Caprock
12. County Lea

15. Elevation (Show whether DF, RT, GR, etc.) 4337' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to clean out 8-5/8" csg. w/bit & csg. scraper and set bridge plug at 1200' with 35' of cement on top of plug. Shoot off 8-5/8" csg. at approx. 600', pull & lay down same. Spot cement plug 50' and 50' out of 8-5/8" csg. Spot cement plug 50' in and 50' out of bottom of 13-3/8" csg. Spot 10 sk. cement plug in top of 13-3/8" csg. Install dry hole marker. Clean location.

Spot cement plug 50' in & 50' out of 8 5/8" csg @ 3665-3665

THE COMMISSION HAS NO NEED TO HOLD HEARINGS TO THE EXTENSION OF PLACING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED	E. B. Fisher	TITLE	Supv. Adm. Ser.
APPROVED BY	Don E. Beyer	TITLE	
CONDITIONS OF APPROVAL, IF ANY:		DATE 6-15-77	
Expires 12/20/77			

RECEIVED

JUL 27 1977

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C.