

NEW MEXICO OIL CONSERVATION COMMISSION

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered

	Indicat	te nature of noti	ce by checking below:		
NOTICE OF INTENTION SHUT-OFF	N TO TEST CASING	G X	NOTICE OF INTENT		
NOTICE OF INTENTION	TO CHANGE PLA	ANS	NOTICE OF INTENT	ION TO PULL OR	
NOTICE OF INTENTION	TO REPAIR WEI	LL	NOTICE OF INTENT	ION TO PLUG WELL	
NOTICE OF INTENTION	N TO DEEPEN WE	ELL			
		Momment,	New Hexico	September 21	, 19 51
			Place	Date	
IL CONSERVATION CO	OMMISSION.				
anta Fe, New Mexico	 ,				
entlemen:					
'ollowing is a notice of in Amerada Petroleum	Cornoration	in work as desc	ribed below at the Y: #!!	Well No. 1 in C	/SW/4
Company or Operator	002 po1 00200	Lease	<u> </u>	Well Noinin	, UR/ 4
Sec. 11 , T	12-S n		N. M. P. M., Wild	cat	
I.a.	, R	, N	N. M. P. M.,	C&T	Field
		County.			
	FIII.I. DETA	ILS OF PROP	POSED PLAN OF W	OBK	
Ran Slumber	ger's Electric	al & Gazzma	Ray Surveys. Ran	1:15 AM, 9/18/51. 92 Joints of 8-5/8	
Ran Slumbers OD 36# H-80	ger's Electric R-3 8-RT SS C	al & Gazzna eg. New, se	Ray Surveys. Ran t at 3623 and ce	92 Joints of 8-5/8 mented with 1000	•
Ran Slumberg OD 36# H-80 sacks regula	ger's Electric R-3 8-RT SS C ar coment mixe	al & Gazzma Sag. New, se d 3% Jel, 4	Ray Surveys. Ran t at 3623 and ce 50 sacks regular	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor	
Ran Slumberg OD 36# H-80 sacks regula cement - to	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor	•
Ran Slumberg OD 36# H-80 sacks regula cement - to	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumber OD 36# N-80 sacks regula cement - tot pump pressu	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumber OD 36# N-80 sacks regula cement - tot pump pressu	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543' at 7 AM, 9/	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum	•
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar cement mixe tal 1500 sacks re 850%. Afte	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543 at 7 AM, 9/ r apprex. 24 hour	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing	
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar coment mixe tal 1500 sacks	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543 at 7 AM, 9/ r apprex. 24 hour	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing	
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar cement mixe tal 1500 sacks re 850%. Afte	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543 at 7 AM, 9/ r apprex. 24 hour	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing	
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar cement mixe tal 1500 sacks re 850%. Afte	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543 at 7 AM, 9/ r apprex. 24 hour Amerada F	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing Company or Operator	on
Ran Slumberg OD 36# H-80 sacks regula cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar cement mixe tal 1500 sacks re 850%. Afte	ial & Gazma isg. New, se id 3% Jel, 4 i. Plug to	Ray Surveys. Ran t at 3623 and ce 50 sacks regular 3543 at 7 AM, 9/ r apprex. 24 hour Amerada F By Position Assists	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing Company or Operator In District Supering	on
Ran Slumberg OD 36# K-80 sacks regular cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar cement mixe tal 1500 sacks re 850%. Afte	es & Gazma esg. New, se d 3% Jel, 4 e. Plug to er W.O.C. fo	Amerada F Position Ray Surveys. Ran And Ce And Ce AMerada F Amerada F Send com	mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing Company or Operator In District Supering munications regarding well	on ntende
Ran Slumberg OD 36# K-80 sacks regular cement - tot pump pressur shut-eff.	ger's Electric R-3 8-RT SS C ar cement mixe tal 1500 sacks re 850%. Afte	es & Gazma esg. New, se d 3% Jel, 4 e. Plug to er W.O.C. fo	Amerada F Position Assista Send com Name	92 Joints of 8-5/8 mented with 1000 and 50 sacks Incor 19/51. Maximum s will test casing Company or Operator In District Supering	on ntende