

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Salt Water Disposal	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name East Caprock SWD
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 2
4. Location of Well UNIT LETTER B 330 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 12S RANGE 32E NMPM.	10. Field and Pool, or Wildcat Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 4354' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ref: Letter dated 4-16-87

Plan to pull and visually inspect 3-1/2" IPC tbg. and nickel plated pkr. Set RBP at 10,700' and isolated suspected 5-1/2" csg. leak w/pkr. Cap RBP w/sand and cement squeeze 5-1/2" csg. leak circulating out 8-5/8" csg. if practical. Test squeeze, drill out and retrieve RBP. Acidize Devonian Zone open hole fr. 11,205 to 11,651' w/5000 gal. 20% NEFE HCL acid. Re-run nickel plated pkr. and 3-1/2" IPC tbg. and resume disposal operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Rebecca Lipman</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>5-8-87</u>
APPROVED BY <u>ORIGINAL SIGNED BY JERRY SEXTON</u> <u>DISTRICT 1 SUPERVISOR</u>	TITLE _____	DATE <u>MAY 11 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECORDED  
MAY 11 1987  
OCD  
HOBBS OFFICE