

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY HOLE	
2. Name of Operator SOUTHWEST PRODUCTION CORPORATION	
3. Address of Operator P. O. Box 936, Roswell, New Mexico 88201	
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 15 TOWNSHIP 12S RANGE 32E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4364' GR	

7. Unit Agreement Name
8. Farm or Lease Name ELLA SPEED
9. Well No. 1
10. Field and Pool, or Wildcat Caprock Queen
12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
11/13/68: Started clean-out of old hole (Originally drilled by Great Western Drilling Co.)	
12/13/68: Cleaned out and drilled to 3048'. Went in with 2-3/8" tubing and open hole packer. Set packer at 2990'. Swabbed open hole 2990-3048'. Recovered drilling mud with no shows of oil or water.	
12/15/68: Acidized with 500 gallons 7½% Acid. Swabbed back Acid water and drilling mud with no shows of oil or water. Pulled 2-3/8" tubing and packer.	
12/16/68: Prep to P&A with cement plugs as follows:	
25 sacks @ TD 3048'	25 sacks @ 300' (bottom of 8-5/8" surf. csg.)
20 sacks @ 2300'	10 sacks @ surface.
20 sacks @ 1450'	
Verbal approval given by CCC-Hobbs.	

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>H. Lee Harvard</u>	TITLE <u>Exploration Manager</u>	DATE <u>January 15, 1969</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>January 15, 1969</u>
CONDITIONS OF APPROVAL, IF ANY:		