NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS REPORTS ON WELES JAN 13 PH 2:52

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of	Report by Checkin	g Below				
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RI OF CASING SH	ESULT OF TEST UT-OFF	<u>x</u>	REPORT REPAIRI	ON NG WELL		
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RI OPERATION	ECOMPLETION		REPORT (Other)	ON		
	(I	January 12,	1955		Midland,	Texas	
Following is a report on the work							
	lling Company					·····	••••
Darrell Smith		, Well No	1	in the	¹ / ₄ SE	.¼ of Sec	15
T. 12-S , R. 32-E , NMPM., U	Indesignated						
The Dates of this work were as folows:.	January 9, 195	5 and Januar	y 11,	1955	·····		•••••
Notice of intention to do the work ((was not) submitted on l	Form C-102 on		ross out incorr	ect words)		, 19,
and approval of the proposed plan ((0	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
	LLED ACCOUNT OF WO	RK DONE AND	RESULI	rs obtain	ED		
	8-5/8" 24# J- 55 ca					lated.	
After 36 ho	urs, the casing wa	s tested w/5	ta q 00	L for 30	minutes.	The	
test was sa	tisfactory and dri	lling contin	ued.				
Witnessed by John Graham (Name		Western Dril	lling (Co.	(Title)	ngin eer .	
Approved: OL CONSERVATION	N COMMISSION	I hereby co	ertify that of my kr	t the information	tion given abov	e is true an	d complet
Q. O. 14.	· Pess	Name	m.	13 W	ilson		
(Nam	(0)	Position			um Engine		**************************************
ℓ	V	Representi	ng Gre	at Weste	rn Drilli	ng Co.	
(Title)	(Date)	Address	Box 1	659, Mid	land, Tex		***************************************

* •