

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-00164
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K 3920
7. Lease Name or Unit Agreement Name CLEVELAND <i>Csm</i>
8. Well No. 1 - 23
9. Pool name or Wildcat <i>East Caprock</i> East Caprock Devonian

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator WAGNER & BROWN	
3. Address of Operator P.O. BOX 1714, MIDLAND, TX 79701	
4. Well Location Unit Letter <u>G</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>23</u> Township <u>12S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4342' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 1) Set CIBP @ approx. 9,000' w/ 35 sx H on top
 - 2) Displace hole w/ 10 ppg mud and spot cmt plugs: 6400' w/ 25sx
5050' w/ 25sx
4350' w/ 35sx
 - 3) Perforate 5-1/2" csg @ 3700' w/ 4 JSPF. Set EZSV @ 3600' and squeeze perfs w/ 50sx.
 - 4) Spot Cmt plug @ 1100' w/ 35 sx.
 - 5) Perforate 5-1/2" csg & 8-5/8" csg @ 400' and squeeze w/ 80 sx.
 - 6) Spot 10 sx plug @ surface. Weld on plate.
 - 7) Install dry hole marker.

Operations to plug to begin upon approval by Oil Conservation Division.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Drew Diggins TITLE Petroleum Engineer DATE 3/3/89
TYPE OR PRINT NAME Drew Diggins, P.E.

TELEPHONE NO. (915) 686-5989

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 9 1989

CONDITIONS OF APPROVAL, IF ANY:

THE COMPLETION OF THIS WORK IS
BEING MONITORED BY THE
OIL CONSERVATION DIVISION
TO DETERMINE

RECEIVED

MAR 8 1989

OCD
HOBBS OFFICE