

COPIES RECEIVED		
DISTRIBUTION		
DATE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-9948	

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator	
Weldon S. Guest & I. J. Welfson	
3. Address of Operator	
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N. M. 88240	
4. Location of Well	
UNIT LETTER C, 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 23 TOWNSHIP 12S RANGE 32E NMPM.	
15. Elevation (Show whether DF, FT, GR, etc.)	
4346 DF	

7. Unit Agreement Name
8. Farm or Lease Name
Mexico "S"
9. Well No.
1
10. Field and Pool, or Wildcat
E. Caprock Wolfcamp
12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned 1/30/74 as follows:

Set cast iron bridge plug @ 8557 & capped with 5 sacks cement  
Cut 5 1/2" casing @ 6314, 4965 & 4645  
Spot plug 4600-4700 across casing stub with 35 sacks  
Spot plug 3690-3790 across 9 5/8" casing shoe with 60 sacks  
Cut 9 5/8" casing @ 750 & pulled  
Spot plug 700-800 with 80 sacks

10 sacks at surface with regulation marker  
Mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Herman Hollis</u>	TITLE <u>Agent</u>	DATE <u>2/8/74</u>
APPROVED <u>Nathan E. Olegg</u>	TITLE <u>OIL &amp; GAS</u>	DATE <u>DEC 11</u>
CONDITIONS OF APPROVAL, IF ANY:		