

OIL CONSERVATION DIVISION
P. O. BOX 2089
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-9946

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEIN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- Injection well

Name of Operator
MURPHY OPERATING CORPORATION

Address of Operator
P. O. Drawer 2648, Roswell, New Mexico 88201

Location of Well
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 23 TOWNSHIP 12 South RANGE 32 East N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4355' D.F.

7. Unit Name
NORTHEAST CAPROCK QUEEN
UNIT

8. Farm or Lease Name
NORTHEAST CAPROCK QUEEN
UNIT

9. Well No.
25

10. Field and Pool, or WHcat
Caprock Queen

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
J.L. OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER perforated & returned well to Injection ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-8-86 RU PU & started flowing well back to pit. Tried to unseat pkr. & could not. Pump dn. backside & press. up to 500# psi. Unseated pkr. & moved dn. 45', moved up 45', no more. Pumped 250 bbls. fresh water around. Think we have salt ring. SDFN.

8-9-86 Finished out of hole w/9-5/8" pkr. All slips on pkr. gone. Pkr. type AD-1 Baker. 12 hrs. working pkr. free. 47 stands & single.

8-10-86 Nippled dn. WH. Picked up 8-1/2" bit & six 3-1/2" D.C. & TIH to 3174' G.L. Picked up power swivel & started drlg. out salt rings. Drilled well out to 3300'. Circ. well for 15 min. & TOH to perf. Perf. as follows:

2997' - 3024' = 27
3103' - 3108' = 5
3115' - 3119' = 4
3137' - 3143' = 6
3190' - 3200' = 10
3212' - 3218' = 6
3231' - 3240' = 9
3248' - 3254' = 6
3278' - 3285' = 7

Total 53 holes @ 1 J.S.P.F. Nippled up WH. SDFN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lois N. Brown TITLE Production Clerk DATE August 12, 1986
Lois N. Brown

PROVED BY Orig. Signed by Paul Kautz TITLE Geologist DATE AUG 18 1986

RECEIVED
AUG 18 1986
O.C.B.
MOBILE OFFICE