| Submit 3 Copies State of New Mexie<br>to Appropriate Energy, Minerals and Natural Reso<br>District Office  |  | Form C-103<br>Revised 1-1-89  |
|--|--|---|
| DISTRICT I<br>P.O. Box 1980, Hobbs, NM 88240<br>OIL CONSERVATION<br>P.O. Box 2088  |  | WELL API NO.  |
| DISTRICT II<br>P.O. Drawer DD, Arlesia, NM 88210<br>DISTRICT III<br>1000 Rio Brazos Rd., Aziec, NM 87410   |  | 5. Indicate Type of Lease   |
|  |  | STATE X FEE   |
|  |  | 6. State Oil & Gas Lease No.<br>LG 6461   |
| SUNDRY NOTICES AND REPORTS ON WELLS<br>( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A<br>DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT"<br>(FORM C-101) FOR SUCH PROPOSALS.)   |  |   |
|  |  | 7. Lease Name or Unit Agreement Name  |
| 1. Type of Well:<br>OIL GAS<br>WELL X WELL OTHER   |  | Lane "B"  |
| 2. Name of Operator  |  | 8. Well No.   |
| Petroleum Production Management, Inc.<br>3. Address of Operator  |  | 3   |
| Suite 200/Sutton Place Bldg. Wichita, Kansa  | is 67202   | 9. Pool name or Wildcat<br>UNdesignated   |
| 10. Elevation (Show whether DF<br>4284' DF   | <i>RKB</i> , <i>RT</i> , <i>GR</i> , <i>etc.</i> )<br>4271' GR   |   |
| NOTICE OF INTENTION TO:<br>ERFORM REMEDIAL WORK PLUG AND ABANDON F<br>EMPORARILY ABANDON CHANGE PLANS C<br>ULL OR ALTER CASING C<br>THER:  | ature of Notice, I<br>SUI<br>REMEDIAL WORK<br>COMMENCE DRILLIN<br>CASING TEST AND C<br>DTHER:  | BSEQUENT REPORT OF:<br>ALTERING CASING<br>IG OPNS. PLUG AND ABANDONMENT<br>SEMENT JOB<br>Progress Report  |
| NOTICE OF INTENTION TO:<br>ERFORM REMEDIAL WORK PLUG AND ABANDON F<br>EMPORARILY ABANDON CHANGE PLANS C<br>ULL OR ALTER CASING C<br>ULL OR ALTER CASING C<br>THER:<br>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g<br>work) SEE RULE 1103.<br>3–28–89<br>Dug out cellar and dug mud pit. Removed dry<br>Shut down for night.<br>3–31–89   | ature of Notice, I<br>SUI<br>REMEDIAL WORK<br>COMMENCE DRILLIN<br>CASING TEST AND C<br>DTHER: <u>Re-Ente</u><br>give perlinent dates, incl   | BSEQUENT REPORT OF:   |
| NOTICE OF INTENTION TO:   ERFORM REMEDIAL WORK PLUG AND ABANDON   EMPORARILY ABANDON CHANGE PLANS   OULL OR ALTER CASING C   OTHER: C   OTHER: C   12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g   work) SEE RULE 1103.   3-28-89   Dug out cellar and dug mud pit. Removed dry   Shut down for night.   | Ature of Notice, I<br>SUI<br>REMEDIAL WORK<br>COMMENCE DRILLIN<br>CASING TEST AND C<br>DTHER: Re-Enter<br>give periment dates, incl<br>whole marker<br>down for nigh<br>Picked up &<br>the plug. Pick<br>d tagged up a     | BSEQUENT REPORT OF:<br>ALTERING CASING<br>IG OPNS. PLUG AND ABANDONMENT<br>SEMENT JOB<br>er - Progress Report<br>wding estimated date of starting any proposed<br>and installed braden head.<br>and installed braden head.<br>at.<br>3 3/4" bit. Drilled 30'<br>sed up total of 6-4 3/4" OD<br>at 2114' KB depth. Drilled |
| NOTICE OF INTENTION TO:<br>ERFORM REMEDIAL WORK PLUG AND ABANDON F<br>EMPORARILY ABANDON CHANGE PLANS C<br>ULL OR ALTER CASING C<br>THER: C<br>THER: C<br>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g<br>work) SEE RULE 1103.<br>3-28-89<br>Dug out cellar and dug mud pit. Removed dry<br>Shut down for night.<br>3-31-89<br>Drilled surface plug to 27' KB depth. Shut<br>4-1-89<br>Rigged up well service unit. Installed BOP.<br>additional cement to 57' KB and broke throug<br>drill collars and 62 joints 2 7/8" tubing and<br>12' to 2126'. Circulated hole clean and shu  | Ature of Notice, I<br>SUI<br>REMEDIAL WORK<br>COMMENCE DRILLIN<br>CASING TEST AND C<br>DTHER: Re-Enter<br>give periment dates, incl<br>whole marker<br>down for nigh<br>Picked up &<br>the plug. Pick<br>at down for nigh  | BSEQUENT REPORT OF:<br>ALTERING CASING<br>IG OPNS. PLUG AND ABANDONMENT<br>SEMENT JOB<br>er - Progress Report<br>wding estimated date of starting any proposed<br>and installed braden head.<br>and installed braden head.<br>at.<br>3 3/4" bit. Drilled 30'<br>sed up total of 6-4 3/4" OD<br>at 2114' KB depth. Drilled |
| NOTICE OF INTENTION TO:<br>ERFORM REMEDIAL WORK PLUG AND ABANDON F<br>EMPORARILY ABANDON CHANGE PLANS C<br>ULL OR ALTER CASING CHANGE PLANS C<br>ULL OR ALTER CASING CHANGE PLANS C<br>ULL OR ALTER CASING C<br>ULL OR ALTER CASING C<br>UTHER:<br>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g<br>work) SEE RULE 1103.<br>3-28-89<br>Dug out cellar and dug mud pit. Removed dry<br>Shut down for night.<br>3-31-89<br>Drilled surface plug to 27' KB depth. Shut<br>4-1-89<br>Rigged up well service unit. Installed BOP.<br>additional cement to 57' KB and broke throug<br>drill collars and 62 joints 2 7/8" tubing and<br>12' to 2126'. Circulated hole clean and shu<br>Thereby certify that the information above is true and complete to the best of my knowledge and bell<br>Mark State of the best of my knowledge and bell<br>Mark State of the best of my knowledge and bell | ature of Notice, I<br>SUI<br>REMEDIAL WORK<br>COMMENCE DRILLIN<br>CASING TEST AND C<br>DTHER: Re-Enter<br>give pertinent dates, incl<br>whole marker<br>down for nigh<br>Picked up &<br>the plug. Pick<br>at down for nigh | ALTERING CASING<br>ALTERING CASING<br>IG OPNS. PLUG AND ABANDONMENT<br>EMENT JOB<br>er - Progress Report<br>uding estimated date of starting any proposed<br>and installed braden head.<br>A.<br>A.<br>B. 3/4" bit. Drilled 30'<br>and up total of 6-4 3/4" OD<br>at 2114' KB depth. Drilled<br>aght.                     |
| NOTICE OF INTENTION TO:   ERFORM REMEDIAL WORK PLUG AND ABANDON   EMPORARILY ABANDON CHANGE PLANS   ULI OR ALTER CASING C   THER: C   12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and g   work) SEE RULE 1103.   3-28-89 Dug out cellar and dug mud pit. Removed dry   Shut down for night.   3-31-8?   Drilled surface plug to 27' KB depth. Shut   4-1-89   Rigged up well service unit. Installed BOP.   additional cement to 57' KB and broke throug   drill collars and 62 joints 2 7/8" tubing and   12' to 2126'. Circulated hole clean and shu   | ature of Notice, I<br>SUI<br>REMEDIAL WORK<br>COMMENCE DRILLIN<br>CASING TEST AND C<br>DTHER: Re-Enter<br>give pertinent dates, incl<br>whole marker<br>down for nigh<br>Picked up &<br>the plug. Pick<br>at down for nigh | BSEQUENT REPORT OF:<br>ALTERING CASING<br>IG OPNS. PLUG AND ABANDONMENT<br>SEMENT JOB<br>er - Progress Report<br>wding estimated date of starting any proposed<br>and installed braden head.<br>and installed braden head.<br>at.<br>3 3/4" bit. Drilled 30'<br>sed up total of 6-4 3/4" OD<br>at 2114' KB depth. Drilled |

Petroleum Production Management, Inc (cont.) Lane "B" NO. 3 (cont.) 4-2-89 Shut down for Sunday. 4 - 3 - 89Drilled 156' of cement to 2282' KB depth and broke through plug. Shut down for night. 4 - 4 - 89Picked up 51 joints 2 7/8" tubing. Tagged up at 3890' KB. Drilled 16' of soft cement to top of 7" casing at 3906' KB depth. Pulled out of hole. Picked up 6" OD bit and tripped in hole. Entered 7" casing and drilled 190' of cement to 4080' KB depth. Circulated to clean hole. Pulled bit 15' off bottom and shut down for night. 4-5-89 Drilled 87' of cement to 4167' KB depth. Went in hole with 6" bit to 5606' KB depth and tagged up. Drilled 2' to 5608'. Pressure tested to 500#. Held steady for 5 minutes. Pulled out of hole. Laid down 6-4 3/4" OD drill collars and 6" bit. Closed in well and shut down for night. 4-8-89 Ran GR-N-CL survey from 4800' to 4600'. Set bridge plug at 4800'. Perforated intervals: 4521'-31', 4542'-52', 4586'-96' and 4610'-20' with 2 JSPF. Ran packer on tubing. Set packer with bottom of tail pipe at 4620' KB depth. Swabbed to seating nipple at 4416' on sixth run. No show of oil or gas. Shut down for night. 4-7-89 Made run with swab to seating nipple at 4416'. No recovery on swab run. No show of oil or gas. Loaded tubing with fresh water. Released packer. Pumped 1 barrel to load hole. Acidized with 2000 gallons 15% HCl. Displaced with 34.4 BFW. Started swabbing. Recovering load water on first 5 runs. Started getting acid water and acid gas on 6th run. Had show of oil on seventh run. Made total of 11 runs. Had 10% oil and 90% formation water on sample from top of last run. Shut down for night. 4-8-89 Ran swab. Swabbed to seating nipple in 5 runs. Recovered 150' fluid on last run. Had 10% oil cut, no acid water or acid gas. Shut down for weekend.

4-9-89 Shut down for Sunday.

•,\* :

Petroleum Production Management, Inc. (cont.) Lane "B" No. 3 (cont.) 4-10-89 Made 9 runs with swab. Started recovering very thick oil and no free water on 6th run. Attempted to release packer with no success. Shut down for night. 4-11-89 Packer still stuck. Ran swab. Swabbed 19 barrels of fluid. Shut down for night. 4-12-89 Ran producing equipment. Hung well on beam. Rigged down well service unit. Shut down for night. 4-13-89 Installed control panel and hooked up to pumping unit motor. Hooked up flow line to pumping tee. Cleaned and leveled location. 4-14-89 Started up pumping unit at 1:00 P.M. Initial production was about 2% oil cut. 4-15-89 Pumped 102 barrels of emulsion to tank. Oil and water not separating in heater treater or tank.

المعقادين وا