N 2, OF COPIE	SRECEIVED		Page 1 of 3 Form C-103
DISTRIE	IUTION		Supersedes Old
SANTA FE	NEW MEXICO	OIL CONSERVATION COMMISSION	C-102 and C-103 more and Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFI	CE		State X Fee
OPERATOR			E 8834
···· <u>·································</u>	SUNDRY NOTICES AND REP	ORTS ON WELLS	
(DO N	DT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEED USE "APPLICATION FOR PERMIT -" IFORM C-	EN OR PLUG BACK TO A DIFFERENT RESERVOIR.	7. Unit Agreement Name
OIL WELL	GAS OTHER-		
The Ma	urice L. Brown Company		8. Furm or Lease Name Lane "B" 674 Ltd.
Address of			9. Well No.
Suite	200/Sutton Place Bldg./Wich	nita. Kansas 67202	3
4. Location of		· · · · ·	10. Field and Pool, or Wildcat
UNIT LETT	ER 660 FEET FROM THE	North LINE AND 1980 FE	ET FROM
1	1	10.0	<u> </u>
THE	West LINE, SECTION 1 TOWNSHI	P 10-D RANGE 33-E	- NMPM. ())))))))))))))))))))))))))))))))))))
mm	15. Elevation (S)	how whether DF, RT, GR, etc.)	12. County
(MIII)		DF; 4271' GR	Lea
2 2222222	Check Appropriate Box To 1	ndicate Nature of Notice, Report	
	NOTICE OF INTENTION TO:	-	QUENT REPORT OF:
PENFORM REMI		BANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER	CHANGE PLA		
		OTHER DWedge Out	casing & Clean out X to 9835'.
OTHER	· · · · · · · · · · · · · · · · · · ·	L]	10 9035.
	roposed or Completed Operations (Clearly state all p	pertinent details, and give pertinent dates, in	acluding estimated date of starting any proposed
	RULE 1103.		
9-06-79	Move in and rig up PBCP Se	ervices, Inc.	
9-07-79	WIH with 6 1/8" OD swedge, up at 5624'. Swedged out	BS, jars, DC's and 2	778" tubing. Tagged
9-08-79	POH. WIH with 4 3/4" bit.	22° 10 30401.	ng ^m oggod up ot
/~00-77	5610.12'. Loaded hole. Ma	de 5' progress to 561	11g. Lagged up at
9-10-79	Drilled 8' to 5623'. Fell	through and went in 1	hole to 9168.901 denth
9-11-79	POH with 4 3/4" bit. WIH	with swedges, BS, jar	s. DC's and tubing.
	POH with 4 3/4" bit. WIH Tagged up at 5595'. Bumpe	ed swedge 22' through	tight casing into clear
	pipe with swedge at 5617.	Worked 2 hours to f:	ree it up. POH
	with swedges.		
9-12-79	WIH with retrievable bridg	ge plug and packer. So	et BP_at 9101'. Spotted
	4 sacks sand on bridge plu	ig. Set packer at 557	1. Pumped into casing
	leak (55871-56181) at 21 H	orm rate at 1050% . He	Leased packer and POH.
9-13-79	WIH with 7" cement retaine Pumped around cement retain	per Set coment nets	paced at 5541',
	and pumped 700 sacks cemer	t. Pulled out of mot	ainer at 2041'. Mixed
	not hold. Reversed out 17	7 barrel cement. then '	lost returns on
	tubing with cement in tubi	Ing. WIH with 6" bit.	Tagged up at 3863'.
	ertify that the information above is true and complete	- ·	
. I hereby c	$= \sum_{i=1}^{N} \sum_{j=1}^{N} \sum_{i=1}^{N} \sum_$		
. I hereby c	A. Almered Bride Stranger	District Engineer	0ATE10-23-79
HUNED			a second state and second s
. I hereby c	Orig Signeff E		OCT 2 6 1979

RECEIVED OCT 2 5 19/5 O.C.D. HOBBS, OFFICE

¢

								Form C-1	
N S. OF COPIES	ALCEIVED								
DISTRIB								Supersede C-102 and	
SANTA FE			NEW MEXICO	OIL CONSE	RVATION C	OMMISSION		Effective	1-1-65
FILE		+1					0.E." .		
		+					St. Martine	-	Type of Lease
U.S.G.S.		+						State X	j Fee
LAND OFFIC	E	∔]						5. State Oil	& Gas Lease No.
OPERATOR	<u> </u>							E 8834	
								1Ť1111	<u>IIIIIIIII</u>
	SL	UNDRY NOTIC	ES AND REP	ORTS ON	WELLS	RENT RESERVOIR.	1	///////	
(DO NO	T USE THIS FORM T	PLICATION FOR PERM	ALT -** (FCRM C+	1011 FOR SUCH	+ FROPOSALS.)			7. Unit Agre	ement Name
		- - -							
WELL Y	GAS WELL	OTHER-						9. Farm or L	ease Name
Name of Cue	rator							-	B" 674 Ltd
The Maur	fice L. B	rown Compa	nv					9, Well No.	
Address of C	perator	-	•					9. WELL NO.	
Suite 20	\mathcal{N}	Place Blo	la Michi	ita. Ka	nsas 6	7202		3	
Location of	Well		1 8 • / 11 ± • • • •						id Pool, or Wildcat
, Loostion of	C	660	FEET FROM THE	North		1980 .	EET FROM	Vada P	enn
UNIT LETTE	LR	,	FEET FROM THE	ALML WILL				11117	
т.	last	4	TOWNSH	10-	3	33 - E		VIIIII	MMMM
THE	lest LINE	SECTION	TOWNSHI	IP I U	MANGE		NMPM.	VIIIII	///////////////////////////////////////
·····	·····	· · · · · · · · · · · · · · · · · · ·	15. Elevation (S.	how whether	DF, RT. GR. e			12, County	VIIIII
					271' GR			Lea	
	WWWW	////////							
16	.i Cl	neck Appropria	ate Box To I	indicate N	ature of No	otice, Repor	t or Uth	er Data	1
	NOTICE	OF INTENTIO	N TO:		1	SUBSI	EQUENT	REPORT	OF:
					1		<u></u>		
PERFORM REME		1	PLUG AND A	BANDON	REMEDIAL WO	DR K			ALTERING CASING
					COMMENCE DI	RILLING OPNS.		P	LUG AND ABANDONMEN
TEMPORARILY				\square	1				
PULL OR ALTER	CASING			NNS 1	CASING TEST	AND CEMENT JOB			
			CHANGE PLA					ing &	Clean out
			CHANGE PLA				it cas	ing & 0	<u>Clean out</u>
OTHER					OTHER S	wedge ou	<u>it cas</u> t	o 9835	1.
OTHER	Proposed or Comp	leted Operations (C			OTHER S	wedge ou	<u>it cas</u> t	o 9835	Clean out te of starting any pro
OTHER 17. Describe F work) SEE	Proposed or Compl CRULE 1103.		learly state all	pertinent det	OTHER S	pertinent dates,	<u>it cas</u> t	estimated da	1 . te of starting any pro
other 17. Describe F work) see Continue	Proposed or Compl CRULE 1103.		learly state all	pertinent det	OTHER S	pertinent dates,	<u>it cas</u> t	estimated da	1 . te of starting any pro
OTHER 17. Describe F work) SEE	Proposed or Compl RULE 1103. d Drilled	annrox, 1	learly state all	pertinent det	other S ails, and give	pertinent dates,	<u>it cas</u> t	estimated da	1 . te of starting any pro
other 17. Describe F work) see ontinue 0-13-79	Drilled retainer	approx. 1	ilearly state all 1201 cem	periment der	other S ails, and give 49831 e	pertinent dates, and broken bole.	<u>it cas</u> t including e out	estimated da	to top of
other 17. Describe F work) see Continue	Drilled retainer	approx. 1 at 5541'	learly state all 120' cemu . Circu	pertinent det	ails, and give 49831 g to clear	pertinent dates, and broken hole.	<u>including</u> e out	estimated da WIH	1. te of starting any pro to top of at 55201.
orner work) see ontinue -13-79	Drilled retainer POH with	approx. 1 at 5541' 6" bit.	learly state all 120' cem . Circu WIH wit	ent to lated h cement t 2 ¹ / ₂ Bl	ails, and give 4983' a to clear nt retai PM at 16	pertinent dates, and broken hole. iner. S 500#. M	<u>including</u> e out et r e ixed a	estimated da WIH tainer and pum	1. te of starting any pro to top of at 55201. aped 700 sa
orner work) see ontinue -13-79	Drilled retainer POH with Pumped t	approx. 1 at 5541' 6" bit. hrough re Displace	learly state all 120' cemu . Circu WIH wit tainer a d with f	ent to lated h cement t 2½ Bl resh wa	ails, and give 49831 a to clear nt retai PM at 16 ater. H	pertinent dates, and broken hole. iner. S 500#. M Pulled o	<u>including</u> e out et r e ixed a	estimated da WIH tainer and pum	1. te of starting any pro to top of at 55201.
orner work) see ontinue -13-79	Drilled retainer POH with Pumped t cement.	approx. 1 at 5541' 6" bit. hrough re Displace	learly state all Circu WIH wit tainer a d with f	ent to lated t 2½ Bl resh wa	ails, and give 49831 a to clear nt retat PM at 16 ater. H H with	pertinent dates, and broken hole. iner. So 500#. M Pulled of tubing.	including including e out et re ixed a ut of	estimated da WIH tainer and pum retain	1. to top of at 55201. aped 700 sa aer. Rever
ormen 17. Describe F work) see ontinue -13-79 -14-79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ b WIH with	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit.	learly state all Circu WIH wit tainer a d with f .) cemen Tagged	ent to lated h cement t 2½ Bl resh wa t. POI up at	ails. and give 4983' a to clear nt retai PM at 16 ater. H H with 1 5517'.	pertiment dates, and broke iner. S 500#. M Pulled of tubing. Drilled	including including e out et re ixed a ut of	estimated da WIH tainer and pum retain	1. to top of at 55201. aped 700 sa aer. Rever
orren 17. Describe F work) see ontinue -13-79 -14-79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ b WIH with	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit.	ilearly state all 120' cemu Circu WIH with tainer a d with f .) cemen Tagged 5' of	ent to lated h cement t 2½ Bi resh wa t. POI up at	ails. and give 4983' a to clear nt retai PM at 16 ater. 1 H with 1 5517'.	pertinent dates, and broke iner. S 500#. M Pulled o tubing. Drilled	including e out et re ixed a ut of 3' of	estimated da WIH tainer and pum retain f hard	'. to top of at 5520'. iped 700 sa ier. Rever cement, re
orres 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ b WIH with tainer a	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille	learly state all Circu WIH wit tainer a d with f .) cemen Tagged d 5' of rd cemen	ent to lated h cement t 2½ Bl resh wa t. PO up at cement	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer	pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541	including e out et re ixed a ut of 3' o . D	o 9835 estimated da WIH tainer and pum retain f hard rilled	'. to top of at 5520'. uped 700 sa her. Rever cement, re 3' of reta
orres 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ t WIH with tainer a Drilled Drilled	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille 13' of ha 75' bard	Tearly state all 120' cemu . Circu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t	ent to lated h cement t 2½ Bi resh wa t. POI up at cement t to r o 5619	ails, and give 4983' a to clear nt retain PM at 16 ater. H H with 1 5517'. to 5522 etainer '. Circ	pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated	including e out et re- ixed a ut of 3' o 3' o 3' o 3' o 1. D	estimated da WIH tainer and pum retain f hard rilled nutes t	'. to top of at 5520'. uped 700 sa ner. Rever cement, re 3' of reta
other 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79	d Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Drilled Ban 10 s	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille 13' of ha 75' hard	learly state all . Circu WIH wit tainer a d with f .) cemen Tagged d 5' of rd cemen cement t	ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to r o 5619	ails, and give 4983' a to clear nt retai PM at 16 ater. H With 4 5517'. to 5528 etainer '. Circo Rigged	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS	including e out et re ixed a ut of 3' o . D 30 mi CO an	estimated da WIH tainer and pum retain f hard rilled nutes t d jette	'. to top of at 5520'. nped 700 sa ner. Rever cement, re 3' of reta to clean ho ed hole dry
other 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -19-79	d Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ t WIH with tainer a Drilled Drilled Ran 10 s	approx. 1 at 5541' 6" bit. hrough re Displace bl. (7 sx 6" bit. nd drille 13' of ha 75' hard tands tub	learly state all . Circu WIH wit tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had	ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to r o 5619 100'. 300' f	ails. and give 4983' a to clear nt retai PM at 16 ater. H With 4 5517'. to 5528 etainer '. Circo Rigged luid abo	pertinent dates, pertinent dates, and broke iner. S 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's	including e out et re ixed a ut of 3' o 3' o 30 mi CO an . No	estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery.
orrer 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -19-79 -20-79	d Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ t WIH with tainer a Drilled Drilled Ran 10 s	approx. 1 at 5541' 6" bit. hrough re Displace bl. (7 sx 6" bit. nd drille 13' of ha 75' hard tands tub	learly state all . Circu WIH wit tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had	ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to r o 5619 100'. 300' f	ails. and give 4983' a to clear nt retai PM at 16 ater. H With 4 5517'. to 5528 etainer '. Circo Rigged luid abo	pertinent dates, pertinent dates, and broke iner. S 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's	including e out et re ixed a ut of 3' o 3' o 30 mi CO an . No	estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery.
orrer 17. Describe F work) SEE ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -19-79 -20-79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ b WIH with tainer a Drilled Drilled Ran 10 s Made rur Had 600	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. 13' of ha 75' hard tands tub with swa of fluid	ilearly state all 120' cemu VIH with tainer a d with f .) cemen Tagged d 5' of rd cement t ing to 6 b. Had in hole	ent to lated h cement t 2½ Bi resh wa t. POI up at cement t to r o 5619 100'. 300' f	ails. and give 4983' a to clear nt retai PM at 16 ater. 1 H with 1 5517'. to 5528 etainer '. Circ Rigged luid abo t run.	pertinent dates, pertinent dates, and broke iner. S 500#. M Pulled o tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat	including e out et re ixed a ut of 3' of 30 mi CO an . No es 30	o 9835 estimated da WIH tainer and pum retain f hard f hard rilled nutes t d jette recove O' fill	'. to top of at 5520'. uped 700 sa her. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over-
ornen 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -19-79 -19-79 -20-79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night ou	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. 13' of ha 75' hard tands tub with swa of fluid a total	Tearly state all 120' cemu VIH wit: tainer a d with f .) cemen Tagged d 5' of rd cemen tement t ing to 6 b. Had in hole of 11 BF	ent to lated h cement t 2½ Bi resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20	ails, and give 4983' a to clear nt retain PM at 16 ater. H H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours.	pertiment dates, pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi	o 9835 estimated da WIH tainer and pum retain f hard f hard rilled nutes t d jette recove O' fill ng and	to top of at 55201. uped 700 sa her. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79	Drilled retainer POH with Pumped t cement. out 1 ¹ / ₂ t WIH with tainer a Drilled Drilled Ran 10 s Made run Had 600' night on with bit	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille 13' of ha 75' hard tands tub with swa of fluid to wash	Tearly state all 120' cemu VIH wit: tainer a d with f .) cemen Tagged d 5' of rd cemen tement t ing to 6 b. Had in hole of 11 BF	ent to lated h cement t 2½ Bi resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20	ails, and give 4983' a to clear nt retain PM at 16 ater. H H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours.	pertiment dates, pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi	o 9835 estimated da WIH tainer and pum retain f hard f hard rilled nutes t d jette recove O' fill ng and	'. to top of at 5520'. uped 700 sa her. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over-
orres 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-20-79 0-21-79	Drilled retainer POH with Pumped t cement. out $1\frac{1}{2}$ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night or with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille 13' of ha 75' hard tands tub with swa of fluid ta total to wash	Tearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off	ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to r o 5619 100'. 300' f on 1s in 20 bridg	ails. and give 4983' a to clear nt retai PM at 16 ater. H with 4 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug.	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple	including e out et re ixed a ut of 3' o 3' o 3' o 3' o 1. D 30 mi CO an . No es 30 casi ted w	estimated da estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove O' fill ng and ashing	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F
other 17. Describe F work) set ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -19-79 -20-79 -21-79	Proposed or Complete Role 1103. d Drilled retainer POH with Pumped t cement. out 1½ th WIH with tainer a Drilled Ran 10 s Made run Had 600 night or with bit and POH. WIH with	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. and drille 13' of ha 75' hard tands tub with swa of fluid t a total t to wash	Tearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off	ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to r o 5619 100'. 300' f on 1s in 20 bridg	ails. and give 4983' a to clear nt retai PM at 16 ater. H with 4 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug.	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple	including e out et re ixed a ut of 3' o 3' o 3' o 3' o 1. D 30 mi CO an . No es 30 casi ted w	estimated da estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove O' fill ng and ashing	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F
orres 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -19-79 -20-79 -20-79 -21-79 -21-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille 13' of ha 75' hard tands tub tands tub of fluid ta total to wash retrievi	learly state all . Circu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	ent to lated h cement t 2½ Bi resh wa t. Pol up at cement t to r o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retain PM at 16 ater. H With 1 5517'. to 5528 etainer '. Circo Rigged luid about run. hours. e plug. trievab.	pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple 1e BP at	including e out et re ixed a ut of 3' o 3' o 3' o 3' o 1. D 30 mi CO an . No es 30 casi ted w	estimated da estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove O' fill ng and ashing	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. nd drille 13' of ha 75' hard tands tub tands tub of fluid ta total to wash retrievi	learly state all . Circu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	ent to lated h cement t 2½ Bi resh wa t. Pol up at cement t to r o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retain PM at 16 ater. H With 1 5517'. to 5528 etainer '. Circo Rigged luid about run. hours. e plug. trievab.	pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple 1e BP at	including e out et re ixed a ut of 3' o 3' o 3' o 3' o 1. D 30 mi CO an . No es 30 casi ted w	estimated da estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove O' fill ng and ashing	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. and drille 13' of ha 75' hard tands tub with swa of fluid t a total t to wash	learly state all . Circu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	ent to lated h cement t 2½ Bi resh wa t. Pol up at cement t to r o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retain PM at 16 ater. H With 1 5517'. to 5528 etainer '. Circo Rigged luid about run. hours. e plug. trievab.	pertiment dates, and broke iner. So 500#. M Pulled of tubing. Drilled 8'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple 1e BP at	including e out et re ixed a ut of 3' o 3' o 3' o 3' o 1. D 30 mi CO an . No es 30 casi ted w	estimated da estimated da WIH tainer and pum retain f hard rilled nutes t d jette recove O' fill ng and ashing	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. ad drille 13' of ha 75' hard stands tub with swa of fluid a total to wash retrievi	learly state all . Circu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	to top of at 5520'. at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F leased BP
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. ind drille 13' of ha 75' hard tands tub with swa of fluid to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	'. to top of at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bbl. (7 sx 6" bit. ind drille 13' of ha 75' hard tands tub with swa of fluid to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101 er	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	'. to top of at 5520'. nped 700 sa ner. Rever cement, re 3' of reta to clean ho ed hole dry ery. Lup over- went in ho sand off H leased BP 10-23-79
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bl. (7 sx 6" bit. and drille 13' of ha 75' hard tands tub with swa of fluid to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101 er	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	'. to top of at 5520'. nped 700 sa ner. Rever cement, re 3' of reta to clean ho ed hole dry ery. Lup over- went in ho sand off H leased BP 10-23-79
ormen 17. Describe F work) see ontinue 0-13-79 0-14-79 0-17=79 0-18-79 0-19-79 0-19-79 0-20-79 0-21-79 0-22-79	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace bl. (7 sx 6" bit. and drille 13' of ha 75' hard stands tub 13' of fluid tands tub of fluid to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101 er	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	to top of at 5520'. at 5520'. aped 700 sa aer. Rever cement, re 3' of reta to clean ho ed hole dry ery. up over- went in ho sand off F leased BP
отнея 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -20-79 -20-79 -21-79 -22-79 -22-79 -22-79 -1.1 Hreby C	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night or with bit and POH. WIH with	approx. 1 at 5541' 6" bit. hrough re Displace obl. (7 sx 6" bit. a drille 13' of ha 75' hard tands tub tands tub of fluid ta total to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101 er	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	'. to top of at 5520'. nped 700 sa ner. Rever cement, re 3' of reta to clean ho ed hole dry ery. Lup over- went in ho sand off H leased BP 10-23-79
отнея 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -17=79 -18-79 -20-79 -20-79 -21-79 -22-79 -22-79 -22-79 -1.1 Hreby C	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night on with bit and POH.	approx. 1 at 5541' 6" bit. hrough re Displace obl. (7 sx 6" bit. a drille 13' of ha 75' hard tands tub tands tub of fluid ta total to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101 er	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	'. to top of at 5520'. nped 700 sa ner. Rever cement, re 3' of reta to clean ho ed hole dry ery. Lup over- went in ho sand off H leased BP 10-23-79
отнея 17. Describe F work) see ontinue -13-79 -14-79 -17=79 -18-79 -19-79 -20-79 -20-79 -21-79 -22-79 -22-79 -1.14-reby с	Drilled retainer POH with Pumped t cement. out 1½ t WIH with tainer a Drilled Ran 10 s Made run Had 600 night or with bit and POH. WIH with	approx. 1 at 5541' 6" bit. hrough re Displace obl. (7 sx 6" bit. a drille 13' of ha 75' hard tands tub tands tub of fluid ta total to wash retrievi	ilearly state all 120' cemu WIH with tainer a d with f .) cemen Tagged d 5' of rd cemen cement t ing to 6 b. Had in hole of 11 BF sand off ng head	peniment det peniment det ent to lated h cement t 2½ Bl resh wa t. POI up at cement t to ro o 5619 100'. 300' fi on 1s in 20 bridg for re	ails, and give 4983' a to clear nt retai PM at 16 ater. I H with 1 5517'. to 5528 etainer '. Circo Rigged luid abo t run. hours. e plug. trievab. of my knowled	pertinent dates, pertinent dates, and broke iner. So 500#. M Pulled o tubing. Drilled brilled s'. at 5541 culated up NOWS ove DC's Indicat Loaded Comple le BP at	including e out et re ixed a ut of 3' o 30 mi CO an . No es 30 casi ted w 9101 er	o 9835 estimated da WIH tainer and pum retain f hard nutes t d jette recove O' fill ng and ashing ". Rel	'. to top of at 5520'. nped 700 sa ner. Rever cement, re 3' of reta to clean ho ed hole dry ery. Lup over- went in ho sand off H leased BP 10-23-79

REDEIVED

OCT 2 5 1979 O.C.D. HOBBS, OFFICE

-	~~~	·	Page 3 of 3
N . OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65
FILE		:	and the second
U.S.G. S .		See the second	Sa. Indicate Type of Lease
OPERATOR			5. State Oll & Gas Lease No.
			- E. 8834
SUNDRY	NOTICES AND REPORTS ON	WELLS	
(DO NOT USE THIS FORD FOR PROPO USE "APPLICATION	FOR PERMIT -" (FORM C-101) FOR SU	CH PROPOSALS.1	7. Unit Agreement Name
1. 01L - 6A5	:		
. Name of Operator	OTHER-	······································	8, Farm or Lease Name
	Company		Lane "B" 674 Ltd.
The Maurice L. Brown	Company		9. Well No.
Suite 200/Sutton Plac	e Bldg./Wichita. H	Cansas 67202	3
4. Location of Well	<u> </u>	•	10. Field and Pool, or Wildcat
C 660	FEET FROM THE North	LINE AND 1980 FEET FRO	Vada Penn
UNIT LETTER 000			
THE West LINE, SECTION	1 TOWNSHIP	3 RANGE 33-E NMP	MMMMMMMMMM
	· · · · · · · · · · · · · · · · · · ·		12. County
	15. Elevation (Show whethe		Lea
	4284' DF		
		Nature of Notice, Report or O	ther Data
, NOTICE OF INT	ENTION TO:	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS		sing & Clean out X
			to 9835'.
OTHER			
17. Describe Froposed or Completed Ope	rations (Clearly state all pertinent de	tails, and give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.			
Continued 9-24-79 WIH with 6"	bit.		
$\alpha \alpha \beta \alpha \beta \alpha \beta \beta$	nnm nm nm nm nm nm nm nm	depth. Made 300' p:	rogress to 9450'.
$\Delta \Delta C \Pi \Omega C have a d A h t$			
			g. Pumped 500 G.
· · · · · · · · · · · · · · · · · · ·		C CONTA	171178 NU# UVSLEP
	into zone.	Well on vacuum at	
of 1000 G. 1	embloc 50 with 500	# oyster snells in .	last 500 G. Well on
waanne oftor	• displacing treatm	ent into zone.	
0 ng 70 Mired and ni	mned 2500 G. of Ha	Tiburton Temploc 5	U with 3750# oyster
shells and d	iisplaced with 800	G. displacement. S	eated of a suddenty.
Could not of	pen packer by pass	DOH Found cnlit	ioint 120 ioints
9-29-79 Tubing broke	e off above packer.	POH. Found split	ugged with Tembloc
down at app	roximately 3750. de	ipth. Hud hodly sol	ugged with Tembloc it and twisted joint
material 2 ;	JOINTS DELOW THE SI	of 269 joints plus	28.60' niece with
205 joints (iown. ruifed total	$\sim 101 \times 10^{-7}$ Jornes prus	TOPOO Prood Hron
bottom 8' f 10-01-79 Attempting	Laut over collons	ed tubing at 84421	depth. Rigged down
DRCD Convio	as. The on $10-5-7$. Will resume work	about 11-1-79.
TDCL PELAIG		af my knowledge and halief	
12. I hereby certify that, the information	above is true and complete to the bei	n or my anowiedge and better.	
M. M. A	ar Alt Sada .)	10 22 70
SIGNED MAMINICES	UTCK TITLE)istrict Engineer	<u>DATE10-23-79</u>
Oriz. Sis	nei H		
			<u>OCT 26 1979</u>
APPROVED BY	TITLE		
CONDITIONS OF APPROVAL, IF ANY	J		

، م

RECEIVED OCT 2 5 1979 O.C.D. HOBBS, OFFICE ала Наў 1993 — Аларана 1993 — Аларана 1993 — Аларана 1994 — Аларана 1994 — Аларана

•