

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SEE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
6. Name of Operator The Maurice L. Brown Company		5. State Oil & Gas Lease No.
7. Address of Operator Suite 200, Sutton Place Bldg. Wichita, Kansas 67202		7. Unit Agreement Name
8. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West THE LINE, SECTION 1 TOWNSHIP 10-S RANGE 33-E NMPM.		8. Farm or Lease Name Lane "B" 674 Ltd.
15. Elevation (Show whether DF, RT, GR, etc.) 4284 KB; 4263 GR		9. Well No. 3
		10. Field and Pool, or Wildcat Vada Penn
		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 5-23-78, Fifty-Five Well Service was rigged up to change the rod pump. The rods and pump were pulled but the tubing was found to be stuck at 5600' depth. All tubing was recovered. The casing was found to be collapsed and was subsequently swedged out from 5587' to 5618'. An attempt was made to repair the casing by cementing; however, the repair was unsuccessful. On 6-21-78, all tubing and rods were layed down and the well was temporarily abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. J. Shoemaker TITLE District Engineer DATE 6-22-78

APPROVED BY John Runyan TITLE Geologist DATE JUN 26 1978

CONDITIONS OF APPROVAL, IF ANY

Expires 6/26/79