

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-105
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2675
7. Unit Agreement Name L L & E Estate
8. Farm or Lease Name L L & E Estate
9. Well No. 1
10. Field and Pool, or Wildcat Middle Lane
12. County Lea

SUNDY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SEE "APPLICATION FOR PERMIT -" (FORM C-111) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Midwest Oil Corp.
3. Address of Operator 1500 Wilco Bldg. - Midland, Texas 79701	4. Location of Well NE 1/4, SECTION 660' FEET FROM THE West LINE AND 2310' FEET FROM THE South LINE, SECTION 14 TOWNSHIP 10-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe in brief or Complete operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures:

13 3/8" Casing @ 400' Circ. W/300 Sx.
8 5/8" Casing @ 4002' Temp. Sur. 2800'
5 1/2" Casing @ 9835' Temp. Sur. 7800'

Plug #1 - CIBP W/35' Cap @ 9550'
Plug #2 - 100' Plug abo-@ 7600' or 100' Plug @ 5 1/2" Stub
Plug #3 - 100' Plug gloriaetta @ 5300'
Plug #4 - 100' Plug in and out of 8 5/8" @ 4002'
Plug #5 - 100' Plug @ Stub of 8 5/8"
Plug #6 - 100' Plug (~~if salt is exposed~~) @ 450' - 350'
Plug #7 - 10' Plug @ 10' to surface

Establish Dry Hole Marker
Clean & Level Location

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Agent for

SIGNED H. D. Oden TITLE Midwest Oil Corp. DATE 12/22/72

APPROVED BY Nathan E. Vlegg TITLE OIL & GAS DIRECTOR DATE DEC 29 1972
CONDITIONS OF APPROVAL, IF ANY: