

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-1565	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Felmont Oil Corporation		8. Farm or Lease Name State F	
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240		9. Well No. 1	
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 11 S RANGE 33 E NMPM.		10. Field and Pool, or Wildcat North Bagley Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4285		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well plugged as follows:

Set cast iron bridge plug @ 10039 & capped with 35' cement, top plug @ 10004
Set cast iron bridge plug @ 9348 & capped with 35' cement, top plug @ 9313
Mixed 10 sacks salt gel with 10# brine water & loaded hole.
Cut & pulled 5 1/2" casing from 4334.
Spotted 15 sack plug 5140 to 5018.
Mixed 8 sacks salt gel with 10# brine water & loaded hole.
Spotted 70 sack plug 4385 to 4169 (covers 5 1/2" casing stub & 8 5/8" shoe).
Mixed 8 sacks salt gel with 10# brine water & loaded hole.
Spotted 35 sack plug 1900 to 1792.
Spotted 10 sacks at surface with regulation marker.
Plugged and abandoned 4/12/76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Wendell Holder</i></u>	TITLE <u>Agent</u>	DATE <u>4/14/76</u>
APPROVED BY <u><i>W.A. Fleeter</i></u>	TITLE <u>Oil & Gas Supervisor</u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 15 1976

OIL CONSERVATION COMM.
HOBBS, N. M.