

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 5 11 41 AM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Cabot Corporation	8. Farm or Lease Name Mary Ellen Dallas
3. Address of Operator P. O. Box 4395, Midland, Texas	9. Well No. 1
4. Location of Well UNIT LETTER P , 660 FEET FROM THE E LINE AND 660 FEET FROM THE S LINE, SECTION 15 TOWNSHIP 11-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat N. Bagley U. Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4249' (Gr.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perforated 5-1/2" casing in the intervals 9017'-9027' and 9037'-9040' with two holes per foot. Ran tubing with straddle packers, washed perforations with 1000 gallons of mud acid and treated with 3000 gallons of regular acid. Swabbed back acid water and load, pulled straddle packers. Ran tubing and rods, put well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Percy C. Ogilvie TITLE Dist. Prod. Sup't. DATE 8-4-65

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: