

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-7332

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator Falmont Oil Corporation	8. Farm or Lease Name State 262	
3. Address of Operator c/o Oil Reports & Gas Services, Box 763, Hobbs, New Mexico	9. Well No. 1	
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 11S RANGE 33E NMPM.	10. Field and Pool, or Wildcat North Bagley	
15. Elevation (Show whether DF, RT, GR, etc.) 4152	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 6/23/70 as follows:

25 sack plug 8678 to 8472
Cut and pulled 5 1/2" casing from 4160
35 sack plug 4160 to 4067
35 sack plug 3920 to 3828 (9 5/8" shoe @ 3875)
10 sack plug at surface with marker
Mud between all plugs.

Location to be cleared and levelled and ready for inspection 8/1/70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>A. L. Smith</u>	TITLE <u>Agent</u>	DATE <u>6/26/70</u>	
APPROVED BY <u>John W. Runyon</u>	TITLE <u>Geologist</u>	DATE <u>JUL 28 1971</u>	
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED

JUN 20 1970

OIL CONSERVATION COMM.
HOBBS, N. M.