

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUS BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <i>7-1-1-1-1</i>
2. Name of Operator Cabot Corporation	8. Farm or Lease Name State of New Mexico
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M.	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1970</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) 4253' D.R.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUS AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUS AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Propose to spot a 25 sx cement plug from 9445'-9458'.
- Propose to spot a 25 sx cement plug at 5 1/2 casing stub at 6000'.
- Propose to spot a 25 sx cement plug at 8-5/8 casing shoe at 3850'.
- Propose to spot a 25 sx cement plug at 8-5/8 casing stub at 1000'.
- Propose to spot a 25 sx cement plug at 13-3/8 casing shoe at 350'.
- Propose to spot a 10 sx cement plug at surface.
- Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Joe D. Ramey* TITLE Agent DATE 1/7/72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE JAN 26 1972

CONDITIONS OF APPROVAL, IF ANY: