

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
(USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Cabot Corporation	8. Farm or Lease Name Humble State
3. Address of Operator c/o Hobbs Pipe And Supply Co., Box 2010, Hobbs, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Locality <u>N. Bagley (Penn)</u>
15. Elevation (Show whether DF, RT, GR, etc.) 4254' D.F.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Propose to spot a 25 sx cement plug from 8668-8689'.
- Propose to spot a 25 sx cement plug at 5 1/2 casing stub at 6000'.
- Propose to spot a 25 sx cement plug at 9-5/8 casing shoe @ 3800'.
- Propose to spot a 25 sx cement plug at 9-5/8 casing stub at 1000'.
- Propose to spot a 25 sx cement plug at 13-3/8 casing shoe at 350'.
- Propose to spot a 10 sx cement plug at surface with marker.
- Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 2/10/72

APPROVED BY Joe D. Ramey TITLE Dist. 1, Supv. DATE FEB 14 1972

CONDITIONS OF APPROVAL, IF ANY: