

COPIES RECEIVED		
CONTRIBUTION		
FEE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-1347

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State BT "C"	
3. Address of Operator Drawer "D", Monument, New Mexico 88265	9. Well No. 4	
4. Location of Well UNIT LETTER M 660 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 35 TOWNSHIP 11-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Bagley Penn.	
15. Elevation (Show whether DF, RT, GR, etc.) 4254' DF	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Set 5-1/2" bridge plug at 8500' with 4 sx. cement on top. Set 5-1/2" bridge plug at 6250' with 4 sx. cement on top. Tested 5-1/2" casing and bridge plug with 1500#. Held O.K. Ran 2-3/8" tubing and displaced hole with mud. Cut and pulled 5-1/2" casing from 4318'. Ran tubing and spotted 50 sx. cement plug at 4360' and 50 sx. cement plug at 3830'. Cut and pulled 8-5/8" casing from 188'. Set 70 sx. cement plug at 230'. Set 10 sx. cement plug at surface with permanent dry hole marker. All plugs were displaced with mud. Well P & A 2-9-74.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>M. D. Black</u>	TITLE <u>Supver., Admin. Services</u>	DATE <u>2-15-74</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		