

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01032
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STATE BD
8. Well No. 1
9. Pool name or Wildcat BAGLEY SILURO DEVONIAN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator ORYX ENERGY COMPANY	
3. Address of Operator P.O. BOX 2880, DALLAS, TX 75221-2880	
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>12S</u> Range <u>33E</u> NMPM LEA	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4243' D.F.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-27-93 MIRU. PULL TBG TO 80000 #/20000 # OVER WT  
7-28-93 PUMP 220 BBLS FW DOWN ANUL/WORKED TBG 2 HRS. UNABLE TO GET SLIPS OUT/ CUT OFF  
WELLHEAD/REMOVED SLIPS/TBG CRIMPED @ SLIPS  
7-29-93 TBG STUCK @ PUMP. CUT TBG @ 7234'  
7-30-93 CUT CABLE @ 7235 POH W/ 1" RODS  
7-31-93 UNABLE TO MOVE TBG. TBG 100% STUCK @ 6290' 100% FREE @ 6205'/ CUT TBG @ 6198'  
8-3/8-12-93 RIH W/ SPEAR, BS & JARS 2 7/8 WS AND FISH/ REC COPPER WIRE DOWN TO 1' CABLE  
8-13-93 CLEAN OUT 6365'-6370'  
8-14-93 CLEAN OUT 6370'-6373'/ RIH W 6" OD WO SHOE 1 JT 5 3/4" WP & JARS ON 2 7/8 TBG, WASH  
OVER CABLE 6373' TO 6374 1/2'  
8-17-93 TIH MILL W WO SHOE 6374 1/2 TO 6375 1/2 IN 8 HRS.  
8-18-93 RIH W 7" PKR ON 2 7/8" WS & SET @ 6090'/LOAD 7" CSG & COMM TO TBG/RESET PKR @ 5993',  
LOAD 7" CSG & TEST TO 500#/ SWAB WELL DRY REC 34 BW NO OIL NO GAS  
8-19/20-93 RAN SWAB 1 RUN REC 100% WTR./ LEFT WELL TA 5X

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Peggy Snyder TITLE PRORATION ANALYST DATE 08-30-93

TYPE OR PRINT NAME PEGGY SNYDER

TELEPHONE NO. 214-715-3233

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

JUL 14 1994

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: