

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM 211	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.	8. Farm or Lease Name State C A/C 1
3. Address of Operator P. O. Box 1861, Midland, TX 79702	9. Well No. 4
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 12-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Devonian
11. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Chang in procedure - deepen thru Devonian & convert to Salt Water Disposal	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Steps 1 thru 12 of original procedure have been completed.

Have now drilled out to the Shoe jt. in the casing to 11005'.

There is some junk in the hole that we have not been able to recover.

Propose to:

- 1) Set a whipstock in 7" csg at approx. 10970'. Drill out around junk in hole, (approx 50'). Continue with procedure to deepen well to 11,430'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED De Ann Kemp TITLE Associate Acct. DATE 10-29-84

ORIGINAL SIGNED BY JERRY SEATON

APPROVED BY DEAN J. SEATON TITLE ASSOCIATE ACCOUNTANT DATE NOV - 1 1984

CONDITIONS OF APPROVAL, IF ANY: