

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Amerada Hess Corporation	5. State Oil & Gas Lease No.
3. Address of Operator Drawer "D", Monument, New Mexico 88265	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>12-S</u> RANGE <u>33-E</u> NMPM.	8. Farm or Lease Name E.E. Mathers
	9. Well No. 3
	10. Field and Pool, or Wildcat Bagley Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4254'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to:
Set bridge plug at 7000' with 35' cement on top of plug. Cut 5-1/2" casing at 5617'.
Spot 100' plug in top of 5-1/2" casing. Spot 100' cement plug at 5129'.
Spot 100' cement plug from 3730' to 3830'. Cut 7-5/8" casing at 1033'.
Spot 100' cement plug from 1083' to 983'. Spot 100' cement plug from 265'
to 365'. Spot 10' cement plug at surface, install dry hole marker.
Plug and abandon.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>M. J. Blach</u>	TITLE <u>Supver., Admin. Services</u>	DATE <u>12-14-73</u>
APPROVED BY <u>Joe D. Ramsey</u> Dist. I, Supv.	TITLE _____	DATE _____

CONDITIONS OF APPROVAL, IF ANY: