

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01804
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McNulty
8. Well No. 1
9. Pool name or Wildcat Jenkins, NW (San Andres)

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Western Reserves Oil Company Inc.
3. Address of Operator P. O. Box 993, Midland, Texas 79702	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>south</u> Line and <u>1980</u> Feet From The <u>west</u> Line Section <u>3</u> Township <u>9 south</u> Range <u>34 east</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4254 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <u>Reentry Operations</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU DA&S Rig No. 176 on 10-29-91. Commence drilling out well. Drilled out cement plug No. 1 at 45'. Cleaned out well to 4104'. Drilled out cement plug No. 2 at 4,104'. Cleaned out well to 4,750'. On 11-07-91 ran 147 joints of 5½", 17 #/ft, J-55, LT&C casing. Ran 4720.81' overall, set at 4739.81' KB elev. Cement well with 250 sacks 50:50 Pozmix "C" w/2% bentonite. Plug down 6:22 pm CST 11-01-91. WOC. Will perforate and acidize San Andres at approximately 4610-4620 on 11-11-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christopher P. Renaud TITLE Engineer DATE 11-08-91  
(915)  
TYPE OR PRINT NAME Christopher P. Renaud TELEPHONE NO. 685-3211

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY JERRY SEXTON TITLE Assistant Secretary DATE 11-08-91

CONDITIONS OF APPROVAL, IF ANY: