				Supersedes Old
DISTRIBUTION				C-102 and C-103
SANTA FE	NEV	MEXICO OIL CONSERVAT	ION COMMISSION	Effective 1-1-65
FILE				5a. Indicate Type of Lease
U.S.G.S.				State Fee
LAND OFFICE				5, State Oil & Gas Lease No.
OPERATOR				E-8447
	CUNDOV NOTICES	AND DEDODES ON WELL	ς	
(DO NOT USE THIS F Us	FORM FOR PROPOSALS TO DRILL SE "APPLICATION FOR PERMIT -	AND REPORTS ON WELL OR TO DEEPEN OR PLUG BACK TO A OR TO DEEPEN OR PLUG BACK TO A OR TO DEEPEN OR PLUG BACK TO A	DIFFERENT RESERVOIR.	7. Unit Agreement Name
I. OIL GA	S OTHER-			8. Farm or Lease Name
2. Name of Operator				Gulf State
A. F. Roberts,	Jr.			9. Weli No.
3. Address of Operator c/o Oil Report	s & Gas Services,	Inc., Box 763, Hob	ba, New Mexico	1
4. Location at Well		FROM THE North		10. Field and Pool, or Wildcat Inbe Permo Penn
UNIT LETTERA				<i>MIIIIIIIIIIIIIIIIIIIIIIIIII</i>
THE East	LINE, SECTION	TOWNSHIP 11 S	RANGE 54 E NMPM	
mmm	15. 1	Elevation (Show whether DF, RT	, GR, etc.)	12. County
		4205		Lea
16.	Check Appropriate	Box To Indicate Nature o:	of Notice, Report or Of Subsequen	ther Data TREPORT OF:
	_			
PERFORM REMEDIAL WORK			DIAL WORK	ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON			ENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING			G TEST AND CEMENT JOB	
		· · · · · · · · · · · · · · · · · · ·	HER	
		1 11		
17. Describe Proposed or work) SIEE RULE 110	Completed Operations (Clear	ly state all pertinent details, an	d give pertinent dates, includin	g estimated date of starting any proposed
17. Describe Proposed or work; SEE RULE 110	completed Operations (Clear 3.) t iron bridge plug Shot 4 1/2" casis 100' cement plug Shot 8 5/8" casis 100' cement plug 100' cement plug 100' cement plug 100' cement plug	g at 9700, cap with ng at 6297, 5994, 50 at 4694 at 4012 ng at 1290 and 1200 at 2440 at 2085 at 1200 at 415 lug at surface. In	35' cement on top 581, 5394, 7074 and and pulled	of plug. 1 4694 and pull ed
17. Describe Proposed or work; SEE RULE 110 Set cas	completed Operations (Clear 3.) t iron bridge plug Shot 4 1/2" casin 100' cement plug 100 cement plug 100 cement plug 10 sack cement plug	g at 9700, cap with ng at 6297, 5994, 50 at 4694 at 4012 ng at 1290 and 1200 at 2440 at 2085 at 1200 at 415 lug at surface. Im plugs	35' cement on top 581, 5394, 7074 and and pulled stalled dry hole ma	of plug. 1 4694 and pull ed