

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8447

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator A. F. Roberts, Jr.	8. Farm or Lease Name Gulf State
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER C , 660 FEET FROM THE North LINE AND 1834.8 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 11 S RANGE 34 E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4212 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug for abandonment as follows:
Set cast iron bridge plug at 9700' & cap with 35' cement
Cut & pull 5 1/2" casing from approximately 8000'
100' plug across 5 1/2" casing stub
100' plug at top of Abo at 7655
100' plug at top of Glorieta at 5390
100' plug across 8 5/8" casing shoe at 4006
Cut & pull 8 5/8" casing from approximately 1500'
(Note: top of Salt at 2085, base of Salt at 2440; if 8 5/8 casing pulled from below these points a 100' plug at top of Salt and a 100' plug at base of Salt)
100' plug across 8 5/8" casing stub
100' plug across 13 3/8" casing shoe at 431'
10 sack plug at surface with regulation marker
9.5# mud between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wanna Hollis TITLE Agent DATE 1/19/73

APPROVED BY Joe D. Raley TITLE Dist. ISS. Div. DATE 2/20/73
CONDITIONS OF APPROVAL, IF ANY: