

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY R H. Fulton P. O. Box 1526, Lubbock, Texas
(Address)

LEASE Betenbough WELL NO. 1 UNIT N S 11 T 98 R 35E
DATE WORK PERFORMED April 7, 1965 POOL Undesignated

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Halliburton - pump 25 sack cement plug at 4770 feet.
Pulled tubing and loaded hole
Halliburton - pump 10 sack cement plug in top of hole
Install permanent marker
Clean up location

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name Leslie A. Clement
Title _____
Date _____

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name Floyd Hancock Floyd Hancock
Position Controller
Company R. H. Fulton