

Markham No. 2 SWD (cont.)

11-16-89

Shut down for Sunday.

11-17-89

Pulled out of hole with HOWCO retrievable bridge plug. Picked up Baker anchor-catcher assembly and tripped in hole on 106 joints 2 7/8" OD, EUE, 8RT Duo-Lined tubing and 202 joints 2 3/8" OD, EUE, 8RT non-coated tubing. Latched into Baker Model "D" packer at 9328' depth. Landed tubing on head flange leaving 15,000# tension on tubing. Pumped 280 BFW down casing and shut down for night.

11-17-89

Completed loading casing with an estimated 50 BFW. Pressured casing to 500#. Recorded on Kenneth Tank Service pressure recorder for 30 minutes. No leak off in 30 minutes. Rigged down well service unit and restored well to disposal service. Will install new plastic coated tubing string in approximately 2 weeks.

NOTE: Pressure chart enclosed.