

UNITED STATES N. M. OIL CONS. COMM. DEPARTMENT OF THE INTERIOR BOX 1980 GEOLOGICAL SURVEY HOBBS, NEW MEXICO 88240

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0450847

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal A-13

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Bough Permo Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 13, T9S, R35E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Marks & Garner Production Company

3. ADDRESS OF OPERATOR

P. O. Box 763, Hobbs, NM 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface

660' FSL & 1980' FWL of Sec 13

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4108 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☒

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Rigged up to plug 7/7/83. Ran tubing, found salt rings. Drilled and circulated hole clean to top of collapsed casing at 6989. Attempted to go in hole with retainer, unable to get down with retainer. Ran casing scrapper to 6989. Set retainer at 6950 and squeezed with 100 sacks, maximum pressure 1600#. Spotted 40' cement plug on top of retainer. Spot 100' plug from 4110 to 4210, 100' plug from 2740 to 2840, 100' plug from 2150 to 2250 and 100' plug from 350 to 450. Set 50' plug at surface with regulation marker. Mud between all plugs. Operations witnessed by Ralph Dilly. Work completed 7/16/83. Surface will be cleaned and made ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Donna Wells*

TITLE

Agent

DATE

7/18/83

(This space for Federal or State office use)

APPROVED BY

*Scott Adams*

TITLE

ACTING

DATE

7-22-86

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

DA Donta m