

U. S. DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
N. M. OIL CONS. COMMISSION
P. O. BOX 1847
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" Form 9-332.)

RECEIVED
JUN 8 1983

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR
Marks & Garner Production Company

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

OIL & GAS

ROSWELL, NEW MEXICO

660' FSL & 1980' FWL of Sec 13

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4108 GR

5. LEASE DESIGNATION AND SERIAL NO.

NM-0450847

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal A-13

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Bough Permo Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 13, T9S, R35E

12. COUNTY OR PARISH

Lea

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Found 5 1/2" casing collapsed at 6989. It is proposed to plug and abandon as follows:

Set retainer at 6950 and squeeze with 100 sacks cement.

Leave 35' cement on top of retainer.

Spot 100' plug inside 5 1/2" casing from 4110 to 4210 opposite 7 5/8" casing shoe @ 4160

Spot 100' plug inside 5 1/2" casing from 2740 to 2840 to cover base of salt @ 2740

Spot 100' plug inside 5 1/2" casing from 2150 to 2250 to cover top of salt @ 2250

Spot 100' plug inside 5 1/2" casing from 350 to 450 opposite 10 3/4" casing shoe @ 413

Spot 10 sack plug at surface = 50'

Mud between all plugs and install regulation marker

Location to be clean and levelled.

18. I hereby certify that the foregoing is true and correct

SIGNED

Peter W. Chester

TITLE

Agent

DATE

6/7/83

(This space for Federal or State use only)

(Orig. Sgd.)

APPROVED BY
PETER W. CHESTER

TITLE

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

JUL 14 1983

*See Instructions on Reverse Side

RECEIVED

JUL 18 1983

**O.C.D.
HOBBS OFFICE**