Form 9-331 (May 1963)

UNITED STATES MEN DF THE INTERIOR (Other Instructions reverse side)

		Budget	Bures	u No). 42-I	11424
5.	LEASE	DESIGN.	ATION	AND	SERIAL	NO.

'	LC - 069300					
	RY NOTICES AND REPORTS C rm for proposals to drill or to deepen or plug b. Use "APPLICATION FOR PERMIT—" for such pr		6. IF INDIAN, ALLOT	TTEE OR TRIBE NAME		
1. OH. GAS	7. UNIT AGREEMENT NAME					
WELL WELL 2. NAME OF OPERATOR	J OTHER		8. FARM OR LEASE	NAME		
Amini Oil Cor		Cox - Federal				
3. ADDRESS OF OPERATOR		ļ	9. WELL NO.			
400 Wall Tow	vers West, Midland, Texas 79 ort location clearly and in accordance with any	9701 State requirements.	10. FIELD AND POOL	OR WILDCAT		
See also space 17 below. At surface	Allison Pe	15 m				
		· .	11. SEC., T., R., M., C SURVEY OR A	OR BLK. AND		
660' FNL & 660	6-E	Sec. 1, T-9-S, R-36-E				
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	12. COUNTY OR PAR	ISH 13. STATE			
	4048.40 G.L.		Lea	N. Mexico		
16. No:	Check Appropriate Box To Indicate N		ther Data			
			REPAIRIN	C WELL		
TEST WATER SHUT-OFF FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT		G CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON			
REPAIR WELL	CHANGE PLANS	(Other)				
(Other)		(Note: Report results of Completion or Recompleted	tion Report and Log	form.)		
17. DESCRIBE PROPOSED OR C proposed work. If w nent to this work.) *	OMPLETED OPERATIONS (Clearly state all pertinent vell is directionally drilled, give subsurface locat	: details, and give pertinent dates, i ions and measured and true vertical	ncluding estimated depths for all mark	date of starting any kers and zones perti-		
12-12-69	Rigged up C.E. Knight & Co	o. casing pulling unit.				
12-16-69	Set a 30 sx. cement plug in the 4-1/2" casing @ 9550'. Filled hole					
	9.5# mud. Old casing perfo					
12-17-69	Set a 30 sk. cement plug in	the $4-1/2$ " casing @ 9	3550'. Set a	a third		
	30 sx. cement plug in the 4-	-1/2" casing @ 9550' ·	which held.	Loaded		
	casing with $9.5 \# mud$.					
12-18-69	Shot $4-1/2$ " casing @ 5000'.					
•	casing. Spotted a 25 sx. ce		top of $4-1/3$	2" casing		
	stub. Set a 25 sx. cement p	=				
12-19-69	Shot $8-5/8$ " casing @ 922'.					
	plug @ 922' at top of 8-5/8"					
	379'. Set a 10 sx. cement p	olug in top of surface	casing and i	installed		
	marker.					
5-5-70	Cleaned up lease and location	on. Ready for inspect	ion.			
			· <u>.</u>			
			- <u>1</u>	•		
			-			
18. I hereby certify that th	ne foregoing is true and correct					
SIGNED Fare	\0	Agent	DATE5-	-11-70		
(This space for Federa	l or State office use)		-			
APPROVED BYCONDITIONS OF APP	ROVAL, IF ANY:	APPROVE	D DATE			
			<u> </u>	7.		

MAY 2 & 1970

RECEIVED

AUNA 1970

OLL CONSERVATION COMM. HORBS, N. 11