

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
FILE		
J.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-100
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E 1940
7. Unit Agreement Name
8. Farm or Lease Name Sunray State "A"
9. Well No. 2
10. Field and Pool, or Wildcat Allison Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Cactus Drilling Company
3. Address of Operator P O Box 2068, Hobbs, New Mexico
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East LINE, SECTION 2 TOWNSHIP 9 south RANGE 36 e NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4062 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well plugging performed 3/12-3/15-1965 in the following manner:

Set 15 sx cement plug at 4900'; set 25 sx cement plug at 4115', shoot-off point; set 10 sx cement plug at surface. All intervals between cement plugs filled with mud. Appropriate well marker set at surface to identify the well location and surface returned to natural contour. All equipment has been removed from the lease and location is ready for inspection.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY Geo. W. Bitten TITLE Vice President DATE April 27, 1965.
ED BY Leslie A. Clements TITLE _____ DATE _____
TIONS OF APPROVAL, IF ANY: